12-24N-3W

Dear Emery,

The No. 1 Klinkenbeard was plugged by Empire States Drilling Co. before the rotary moved off, as the Pictured Cliffs was completely shaled out. I believe that Percy Collier was the toolpusher on the rig.

I will be glad to file \*\* the forms, since I am sure that it was plugged Halliburton was there before I left that morning. Let me know if you want me to go ahead and file them.

Regards,

I'll have to look up The

log, and other data

CIL DIST. 3

From the desk of JAY HARRIS Phone: 5-0647

## State of New Mexico Bil Conservation Commission

LAND COMMISSIONER GUYTON B. HAYS MEMBER



1000 RIO BRAZOS ROAD AZTEC STATE GEOLOGIST A. L. PORTER, JR. SECRETARY - DIRECTOR

June 30, 1967

Mr. Jay J. Harris 801 Ridgecrest Drive SE Albuquerque, New Mexico

> Re: Hugh McMillan Klinkenbeard #1 1850/N; 1850/E

Section 12, T 24N, R 3W

Dear Jay:

I am sending a copy of our file for the above well. You will note that we have a scout ticket indicating the well was plugged and abandoned, but we did not receive a plugging report.

I notice that you signed the forms that were filed and I thought it might be possible you could furnish us with a plugging report on the well so we can get it off our backs. At any rate I would certainly appreciate it if you could.

If I can not get some kind of report from someone, we are going to have to go to hearing and have Mr. McMillan and the bonding company show that it was plugged or plug it.

I am enclosing a supply of form C-103 for you to use.

Thank you and best regards.

Yours very truly,

Emery C. Arnold Supervisor, District #3

ECA:mc

Encl.

XERO

COPY