(Feb. 1951)						
		• /	c c			
		1	7			

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa		
Lease No. Si	0807	L5A	
Unit		·	

NOTICE OF IN	ITENTION TO DRILL		X	SUBSEQUENT	REPORT OF V	VATER SHUT-OF	F	
NOTICE OF IN	ITENTION TO CHANGE PL	LANS		SUBSEQUENT	REPORT OF S	HOOTING OR A	CIDIZING	
NOTICE OF IN	ITENTION TO TEST WATE	ER SHUT-OFF		SUBSEQUENT	REPORT OF A	LTERING CASIN	G	
NOTICE OF IN	ITENTION TO RE-DRILL	OR REPAIR WELL		SUBSEQUENT	REPORT OF F	E-DRILLING OR	REPAIR	
NOTICE OF IN	ITENTION TO SHOOT OR	ACIDIZE	-	1				
	ITENTION TO PULL OR A		-	SUPPLEMENT	ARY WELL HIS	TORY		
	ITENTION TO ABANDON							
	(INDICAT	TE ABOVE BY CHECK MAR	RK NAT	URE OF REPOR	T, NOTICE, OR	OTHER DATA)		
			•	*	May 1	0		., 19.5
	radem-Federal		(1	NT)		Œ	,	
ell No	6 is locate		m	line and	1 1300 f	t. from	line of sec.	19
NE/4		24 North		1 West		NMPM		
	and Sec. No.)	(Twp.)	(Ran	ige)	(Meridi New Mex			
CEGG	signated (Field)	(County	or Sut	bdivision)	1109 1107		Territory)	
	Oreund on of the derxick				_			
	and expected depths to	objective sands; show s	izes, w	eights, and len	K	ed casings; ind	icate mudding jo	bs, ceme
	and expected depths to	objective sands; show s ing points, and all	izes, w	eights, and len important pro	gths of propo	ed casings; ind	icate mudding jo	bs, ceme
	set a minimu	ing points, and all	other 3 5/1	important pro	gths of proposed work)	g and cen	ment w/100	1
sacks.	set a minimus To drill w/ro	ing points, and all  a of 100° of 5 otary tools to	5/i	important pro 8" surfa approxi	gths of proposed work)  Ce Casin  mate T.D	g and cer . of 3500	ment w/100	1
sacks. electric	set a minimus Te drill v/roccleg to T.D.	ing points, and all a of 100° of 8 otary tools to If producting	5/i an	8" surfa approxi to set a	gths of proposed work)  ce casin nate T.D pprexima	g and cen . of 3500 tely 3500	ment w/100 )'. To ru )'. Ly''	n n
sacks. electric casing.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and cen . of 3500 tely 3500	ment w/100 )'. To ru )'. Ly''	n n
sacks. electric casing.	set a minimus Te drill v/roccleg to T.D.	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and cen . of 3500 tely 3500	ment w/100 )'. To ru )'. Ly''	n n
sacks. electric casins.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and cen . of 3500 tely 3500	ment w/100 )'. To ru )'. Ly''	n n
sacks. electric casins.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and com of 3500 tely 3500 tured Cli	ment w/100 of 44" liffe sand,	n n
sacks. electric casins.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and cen . of 3500 tely 3500	ment w/100 of 44" liffe sand,	n n
sacks. electric casins.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and com of 3500 tely 3500 tured Cli	ment w/100 of 44" liffe sand,	n n
packs. electric casins.	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all a of 100° of 5 otary tools to If productive /100 sacks.	5/i an le po	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D pprexima	g and com of 3500 tely 3500 tured Cli	ment w/100 of 44" liffe sand,	n n
sacks. electric casing, sand-wa	set a minimum Te drill w/rec leg to T.D. and coment w/	ing points, and all  a of 100° of 8 otary tools to  If productive /100 sacks. 1 run 12 <sup>th</sup> EUE t	5/i an re, to pe	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D  pprexima the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n.
sacks. electric casing, sand-war	set a minimum Te drill w/ro c leg to T.D. and coment w/ ter frac, and	ing points, and all  eff 100° of S  stary tools to  If productive  100 sacks. I  run 12" EUE t	5/i an re, to pe	8" surfa approxi to set a erforate	gths of proposed work)  ce casin nate T.D  pprexima the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n.
sacks. electric casing, sand-wat  I understand ompany	set a minimus Te drill w/re c log to T.D. and cement w/ ter frac, and ithat this plan of work SHAR-ALAN OI	ing points, and all  eff 100° of S  stary tools to  If productive  100 sacks. I  run 12" EUE t	s 5/2 an /e, ' fo potabil	8" surfa approxis to set a erforate	gths of proposed work)  ce casin nate T.D  pprexima the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n.
sacks. electric casing, sand-wat  I understand empany	set a minimus Te drill w/re c log to T.D. and cement w/ ter frac, and ithat this plan of work SHAR-ALAN OI	ing points, and all  a of 100° of S  stary tools to  If productive  100 sacks. I  run 1211 EUE t  must receive approval i	s 5/2 an /e, ' fo potabil	8" surfa approxi to set a erforate	gths of proposed work)  ce casin  nate T.D  pprexima  the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n.
sacks. electric casing, sand-wat  I understand empany	set a minimus Te drill w/re c log to T.D. and cement w/ ter frac, and ithat this plan of work SHAR-ALAN OI	ing points, and all a of 100° of S otary tools to If productive 100 sacks. Tun 12" EUE to must receive approval i	s 5/2 an /e, ' fo potabil	8" surfa approximate as a surfare to set a surfare to set a surfare to surfar	gths of proposed work)  ce casin nate T.D  pprexima the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n
sacks. electric casing, sand-wat  I understand empany	set a minimum Te drill w/ro c log to T.D. and coment w/ ter frac, and that this plan of work SHAR-ALAN OII	ing points, and all a of 100° of S otary tools to If productive 100 sacks. Tun 12" EUE to must receive approval i	other  5 //  5 an  7e, 1  To potabil	8" surface approximate approxi	gths of proposed work)  Ce Casin  nate T.D  pprexima  the Pic	g and com of 3500 tely 3500 tured cli  MA  Oit  before operation and S. Ha	1 5 1961	n
sacks. electric casing, sand-wat  I understand	set a minimum Te drill w/ro c log to T.D. and coment w/ ter frac, and that this plan of work SHAR-ALAN OII	ing points, and all a of 100° of S otary tools to If productive 100 sacks. Tun 12" EUE to must receive approval i	other  5 //  5 an  7e, 1  To potabil	8" surface approximate approxi	gths of proposed work)  ce casin  nate T.D  pprexima  the Pic	g and center of 3500 tured climate (MA)	1 5 1961	n.
sacks. electric casing, sand—wa	set a minimum Te drill w/ro c log to T.D. and coment w/ ter frac, and that this plan of work SHAR-ALAN OII	ing points, and all a of 100° of S otary tools to If productive 100 sacks. Tun 12" EUE to must receive approval i	other  5 //  5 an  7e, 1  To potabil	8" surface approximate approxi	gths of proposed work)  ce casin mate T.D  pprexima the Pic  logical Survey  Rich tle Mgr.	g and com of 3500 tely 3500 tured cli  MA  Oit  before operation and S. Ha	1 5 1961	n

## NEW MEXICO JIL CONSERVATION COMMISSION Well Location and Acreage Dedication Plat

SECTION A.	Date May 11, 1961
Operator Shar-Alan Oil Company Lease	Abraham-Federal ar coofis A
	800 Feet From East Line
County Rio Arriba G. L. Elevation 7463  Name of Producing Formation Pleasured Cliffs	March and served
•	t.
1. Is the Operator the only owner* in the dedicated acreage outlined on	
<ol> <li>If the answer to question One is "No," have the interests of all the agreement or otherwise? Yes</li></ol>	·
3. If the answer to question Two is "No," list all the owners and the awner	LAND ESCRIPTION
	OIL CON. COM.
SECTION S.	
SEC. 1800'-	This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.
	This is to certify that the well location shown on the plat in Section E was plotted from field notes of actual surveys made by me or under my supervision and that the same is true and correct to the best of my knowledge and belief
	Four States Engineering Co. FRANK NOTED WEST MEXICOLD  EARLY COLSTANTE
	Certificate No. 1545