

Jic #1-34

P-34-24N-4W

U.S. Smelting, Ref. & Mining

PC

mm

F.Loc. 850/S; 810/E Elev. _____ Spd. _____ Comp. 1/4/55 TD _____ PB _____
Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg.Perf. _____ Prod. Stim. _____

T
r
a
n
s

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____

TOPS		NITD	X	Well Log	TEST				DATA		
Kirtland		C-102		Plat	Schd.	PC	Q	PW	PD	D	All.
Fruitland		C-103		Electric Log							
Pictured Cliffs		C-104		C-110							
Cliff House				C-122-B							
Menefee		Remarks									
Point Lookout											
Mancos											
Tocito											
Dakota											
Morrison											
Entrada											

P. *Wildcat*

Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec.

No.



United States Department of the Interior

GEOLOGICAL SURVEY
P. O. Box 959
Farmington, New Mexico 87401

December 4, 1980

New Mexico Oil Conservation Division
Attn: Mr. Frank Chavez
1000 Rio Brazos Road
Aztec, New Mexico 87410

Dear Mr. Chavez:

Reference is made to your letter of November 25, 1980 dealing with the status of several Federal wells. The status of these wells are as follows:

1. Mesa Retailers well No. 1 Navajo, SE $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 18, T. 18 N., R. 10 W., has been plugged and abandoned but the operator has failed to submit a subsequent Report of Abandonment.
2. U. S. Smelting, Refining and Mining Company's well No. 1-34 Jicarilla, SE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 34, T. 24 N., R. 4 W. and well No. 1-2 Jicarilla, sec. 2, T. 23 N., R. 4 W. were not drilled.
3. Arwood H. Stowe's well No. 1, 2 and 3 Timmy are still temporarily abandoned.

If you need further information, please advise us.

Sincerely yours,

Bruce Wansley
for James F. Sims
District Oil and Gas Supervisor

