APPROVED APR 30 1953 Alleguere ENGANEER

COPY FOR STATE OF NEW MEXICO OIL CONSERVATION SUBMIT IN TRIPLICATE TO DISTRICT OFFICE

UNITED STATE	S
DEPARTMENT OF THE	INTERIOR
GEOLOGICAL SUR	VEY

Land Office	_
Lease No. SF 078939-C	_
Unit	

NATICE OF INTENTION	TO DRILL		T REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION	TO CHANGE PLANS	SUBSEQUEN	T REPORT OF SHOOTING OR ACIDIZING
	TO TEST WATER SHUT-C	SUBSEQUEN	IT REPORT OF ALTERING CASING
NOTICE OF INTENTION	TO RE-DRILL OR REPAIR	R WELL SUBSEQUEN	IT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION	TO SHOOT OR ACIDIZE.	SUBSEQUEN	T REPORT OF ABANDONMENT
NOTICE OF INTENTION	TO PULL OR ALTER CAS	SING SUPPLEMEN	NTARY WELL HISTORY
	TO ARANDON WELL		
			O OTUGO DATA)
	INDICATE ABOVE BY	CHECK MARK NATURE OF REP	ORT, NOTICE, OR OTHER DATA)
			April 29 , 19.53
		700 (N) 1:	1 2010 ft from E line of sec. 17
			and 2040 ft. from E line of sec. 17
NW NE∕Se	c. 17	19N LiW	N.M.P.M. (Meridian)
(14 Sec. and Sec	k No.)	Candows I	New Mexico
Wildcat	A	(County or Subdivision)	New Mexico(State or Territory)
he elevation of	the derrick noor	above sea level is .6641	
		OF W	
		DETAILS OF WO	
indie	cate muddling jobs,	to objective sands; show si cementing points, and all	izes, weights, and lengths of proposed casings; other important proposed work)
indie	cate muddling jobs,	o objective sands: show si	izes, weights, and lengths of proposed casings; other important proposed work) to 4595.
indic 1-17-53 - TD 1	1695. Spotte Cement	d cement plug 4695	to 4595. weights, and lengths of proposed casings; other important proposed work) to 4595. wow of air, died in 1 hour.
indic 1-17-53 - TD 1 1-20-53 - DST Reco	4695. Spotte Cement 4375 to 4432. overed 90. dri tted cement pl	d cement plug 4695 plug 4525 to 4432 Open 1 hour. Blo	to 4595. ow of air, died in 1 hour. hows. Spotted cement plug 2342 to 2242.
indic 1-17-53 - TD 1 1-20-53 - DST Reco	4695. Spotte Cement 4375 to 4432. overed 90. dri tted cement pl	d cement plug 4695 plug 4525 to 4432 Open 1 hour. Blo	to 4595. ow of air, died in 1 hour. hows. Spotted cement plug 2342 to 2242.
indic 1-17-53 - TD 1 1-20-53 - DST Reco 1-21-53 - Sport 1-23-53 - Ran	cate muddling jobs, 4695. Spotte Cement 4375 to 4432. overed 90. dri tted cement pl and cemented	d cement plug 4695 plug 4525 to 4432 Open 1 hour. Blo lling fluid. No sl	to 4595. weights, and lengths of proposed casings; other important proposed work) to 4595. we of air, died in 1 hours, hows. Spotted cement plug 2342 to 2242.
indicated in the indica	4695. Spotte Cement 4375 to 4432. overed 90. dri tted cement pl and cemented e out rotary t that this plan of wo	d cement plug 4695 plug 4525 to 4432 Open 1 hour. Blo lling fluid. No sl	to 4595. ow of air, died in 1 hourshows. Spotted cement plug 2342 to 2242.
indic -17-53 - TD 1 -20-53 - DST Reco -21-53 - Spor 4-23-53 - Ran Movel I understand	cate muddling jobs, 4695. Spotte Cement 4375 to 4432. overed 90. dri tted cement pl and cemented	d cement plug 4695 plug 4525 to 4432 Open 1 hour. Blo lling fluid. No sl	to 4595. weights, and lengths of proposed casings; other important proposed work) to 4595. we of air, died in 1 hours, hows. Spotted cement plug 2342 to 2242.
-17-53 - TD 1 -20-53 - DST Reco -21-53 - Sport -23-53 - Ran Move I understand operations m	4695. Spotte Cement 4375 to 4432. Overed 90. dri tted cement pl and cemented e out rotary to that this plan of wo hay be commenced.	d cement plug 4695 plug 4525 to 4432. Open 1 hour. Blooming fluid. No slow graph of the cools. Now moving the cools. Now moving the cools. Now moving the cools. Now moving the cools.	to 4595. To died in 1 hourshows. Spotted cement plug 2342 to 2242. With 60 sacks. in cable tools. in writing by the Geological Survey before
indicated and indicated are selected as a selected are selected as a select	cate muddling jobs, 4695'. Spotte Cement 4375 to 4432. overed 90' dri tted cement pl and cemented e out rotary that this plan of wo hay be commenced. overy et al Ope	o objective sands; show sincementing points, and all dement plug 4695 plug 4525 to 4432. Open 1 hour. Blooming fluid. No slow 4332. 7" OD casing at 21 tools. Now moving the must receive approval the erating Account	to 4595. to 4595. wo of air, died in 1 hour. hows. Spotted cement plug 2342 to 2242. % with 60 sacks. in cable tools. in writing by the Geological Survey before
indicated and indicated are selected as a selected are selected as a select	4695. Spotte Cement 4375 to 4432. Overed 90. dri tted cement pl and cemented e out rotary to that this plan of wo hay be commenced.	o objective sands; show sincementing points, and all dement plug 4695 plug 4525 to 4432. Open 1 hour. Blooming fluid. No slow 4332. 7" OD casing at 21 tools. Now moving the must receive approval the erating Account	to 4595. To died in 1 hourshows. Spotted cement plug 2342 to 2242. With 60 sacks. in cable tools. in writing by the Geological Survey before

 \simeq

Č VS

 $\mathbf{x}_{\mathbf{x}} = \mathbf{x}_{\mathbf{x}} + \mathbf{x}_{\mathbf{x}} +$

The second with the second seco

Programme (Contraction