
Form 9-331 (May 1962)

UNITED STATES UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on re-

Form approved. Budget Bureau No. 42-R1424.

		I-89-IND-57				
	SUNDRY NO (Do not use this form for Use "AF	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
1.	Ose AI	Navajo Tribe				
	OIL K GAS OTE	7. UNIT AGREEMENT NA	ME			
2.	NAME OF OPERATOR Eastern Petroleum Company			8. FARM OR LEASE NAME Navajo Zable Mesa		
3.	P. O. Eox 226, Farmington, New Mexico 87401			9. WELL NO. #14		
1.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below (At surface			Table Mesa-Dakota		
	2420 FWL - 2420 FEL			11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA		
				Sec.3,T27N,R17W		
11.	PERMIT NO.	15. ELEVATIONS (Show will 5338	nether DF, RT, GR, etc.)	12. COUNTY OF PARISH San Juan	13. STATE New Mexico	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
		INTENTION TO:		SUBSEQUENT REPORT OF:		
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	VELL	
	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	SING	
	REPAIR WELL	ABANDON*		ABANDONMEN	T*	
	(Other) (Other) (Other) (Other) (Other) (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			on Well		
17.	DESCRIBE PROPOSED OR COMPLETE proposed work. If well is d nent to this work.) *	D OPERATIONS (Clearly state all irectionally drilled, give subsurfa	pertinent details, and give pertinent da ace locations and measured and true ver	to: including estimated data		
	Propose to aband	on and set the foll	owing plugs:			
	Dakota	1370-1238 w/16	sx			
	Top Plug	0-10 w/3s				
	Will erect a 4'4	' marker and clean	up location. Csg. cemen	nted top to botto	m -	



A		
18. I hereby certify that the foregoing is the and correct SIGNED Ablut (Celly	Vice President	12-15-72
(This space for Federal or State office use)		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE