

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.

SF 065557

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF OPERATOR
Producing ROYALTIES INC.
2. ADDRESS OF OPERATOR
Box 1071 LUBBOCK, TEXAS 79408
3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 800' FN L, 440' FEL Sec 13,
T29N, R12W, SAN JUAN Co. NM
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
S673 DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CARROLL - CORNELL

9. WELL NO.

5

10. FIELD AND POOL, OR WELL-CAT

FULLER - KUTE PC

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 13, T29N, R12W
N.M.M.

12. COUNTY OR PARISH 13. STATE

SAN JUAN N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well has been plugged & abandoned as follows:

6-10-76 Move in equip., Circulate hole w/ mud., Spot 50sx plug 1877' to 1735', Pulled 1" tbg.

6-11-76 Perf 4 hole @ 650', Ran tbg to 650' Spot 50sx @ 650', Pull tbg. Squeezed 30sx thru Perfs. Set P&A marker w/ 10sx Clean up loc.



18. I hereby certify that the foregoing is true and correct

SIGNED

Larry G Bedford

TITLE

Agent for Operator

DATE

6-12-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 11 1977