(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Senta Po-
	02811E

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Unit Crenter A
SUNDRY NOTICES AND REPORTS ON	WELLS 4AY 3 0 1951

OIL CON. COM. NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF WATER SHUT-OFF. NOTICE OF INTENTION TO CHANGE PLANS..... SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING... NOTICE OF INTENTION TO TEST WATER SHUT-OFF.... SUBSEQUENT REPORT OF ALTERING CASING... NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR... NOTICE OF INTENTION TO SHOOT OR ACIDIZE. SUBSEQUENT REPORT OF ABANDONMENT NOTICE OF INTENTION TO PULL OR ALTER CASING..... SUPPLEMENTARY WELL HISTORY..... NOTICE OF INTENTION TO ABANDON WELL.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 4 Grenier is located	1 222 ft. from N line	and	
15 / 15 / 1 Sec. 7 ()4 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)	
(Field) ground	(County or Subdivision)	(State or Territory)	
The elevation of the derrick flow		€. ft.	

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was shot May 28, 1991 from 5096 to Total Tepth 5106 with 780 qts. Mitro Clycerin.

Well tested 555 Mef before shot and 2700 Mef 20 hours after shot.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	A2TOC DIL E CAN COMMENT	·		
Address	110h Burt Building			
	Cellas 1. Texas	By It C 12 outgomery (y)		
		Title Prilling Superintendent		