

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. SF - 078115
2. NAME OF OPERATOR Antec Oil and Gas Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Drawer 570, Farmington, New Mexico	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	8. FARM OR LEASE NAME Crescent
9. PERMIT NO. 990 FSL & 1650 FSL, Sec. 6-31N-11W	9. WELL NO. 1
10. PROVISIONS (Show whether DE, SE, SW, etc.) SEED 1W	10. FIELD AND POOL, OR WILDCAT Blanco Mesavende
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 6-31N-11W	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
12. COUNTY OR PARISH San Juan	12. COUNTY OR PARISH 13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☒	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to:

Pull 2-3/8" tubing, 112 tubing is stuck cut off.
Set cement retainer
Squeeze open hole
Set whipstock & approximately 5100
Cut window in 5 1/2" casing
Drill through Point Lookout formation to TD of approximately 7700
Run 1 1/2" liner
Perforate and sand-water free Point Lookout
Run 1 1/2" tubing.



RECEIVED

NOV 15 1968

U. S. GEOLOGICAL SURVEY

APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____		