Form 3160 HOBBS OCD FORM APPROVED UNITED STATES OMB No. 1004-0137

OMB No. 1004-0137

Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT

1625 N

OMB No. 1004-0137

Expires: July 31, 2010

1625 N

District I (August 2007) 1625 N. French Drive SUNDRY NOTICES AND REPORTS ON WELLS

Description of the proposal of the propos Hobbs, NMIn 8824 gutee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. X Oil Well Gas Well Other West Cap Queen Sand Unit #2 9. API Well No. 2. Name of Operator 30-005-01096 Celero Énergy II, LP 3a, Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 400 W. Illinois, Ste. 1601 Midland TX 79701 (432)686-1883 Caprock; Queen Location of Well (Footage, Sec., If, R, M., or Survey Description) 660' FNL & 1979' FEL 11. Country or Parish, State Chaves, NM (B) Sec 17, T14S, R31E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Acidize Deepen Production (Start/Resume) X Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation X Other Reactivate Casing Repair New Construction Recomplete Subsequent Report injector Plug and Abandon Temporarily Abandon Change Plans Water Disposal Final Abandonment Notice Convert to Injection Plug Back 13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) MIRU well service rig. 2. TOOH w/ injection tbg. 3. Clean out well to TD.

- Test csa.
- 5. TiH w/ tbq & pkr.
- 6. Run MIT.
- 7. Place well on injection.

Approval Subject To Calling The BLM Roswell Field Office At Least 24 Hours Prior To The Scheduled Mechanical Integrity Test (MIT). For Wells In Chaves And Roosevelt County, Call (575) 627-0205 Or After Office Hours Call (575) 420-2832.

APPROVED FOR 3 MONTH PERIOD ENDING

110

	YYUD-OCD 7/20/2011	
14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Lisa Hunt	Title Regulatory Analyst	
Signature Lisa Hunt	Date 06/30/2011	
THIS SPACE FOR FEI	DERAL OR STATE OFFICE USE	******

Approved by

PETROLEUM ENGINEER

JUL 1 2 2011 Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.