

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 June 19, 2008

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

HOBBS OGD
 SEP 16 2011

WELL API NO. 30-025-40148	✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	✓
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name V LAUGHLIN	✓
8. Well Number 011	✓
9. OGRID Number 873	✓
10. Pool name or Wildcat MONUMENT; ABO, SOUTHEAST (96764)	✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3553 GR	

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Well Gas Well Other

2. Name of Operator
APACHE CORPORATION

3. Address of Operator
303 VETERANS AIRPARK LANE, STE 3000; MIDLAND, TX 79705

4. Well Location
 Unit Letter B : 330 feet from the N line and 2220 feet from the E line
 Section 9 Township 20S Range 37E NMPM County LEA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: COMPLETION <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-29-2011 RIH WITH 3 1/8" SLICK GUNS AND PERF ABO @
 7095'-7097', 7132'-7135', 7137'-7140', 7144'-7148', 7152'-7155', 7160'-7163', 7166'-7169', 7172'-7176', 7178'-7182', 7195'-7198',
 7207'-7209', 7216'-7226', 7236'-7246', 7248'-7253', 7256'-7264', 7274'-7276', 7278'-7282', 7292'-7296', 7344'-7346', 7348'-7350',
 7373'-7275', 7380'-7383', 7410'-7414', 7424'-7428', 7430'-7433', 7438'-7440', 7442'-7445', 7450'-7454', 7476'-7479', 7484'-7486',
 7488'-7490'. 2 SPF. 120 DEG PHASE. 288 HOLES. ACIDIZE ABO PERFS WITH 6000 GALS 15% NEFE HCL ACID.
 8-3-2011 PMP 2000 GALS 20% ACID. PUMP 10000 GALS BFRAC. PMP 10000 GALS 20% GEL ACID. PMP 8000 GALS ACID.
 PMP 2100 GALS TREATED WTR. PMP 2000 GALS ACID. PMP 4200 GALS BFRAC 20. PMP 10000 GALS GEL ACID. PMP 8000
 GALS ACID. PUMP 2100 GALS TREATED WTR. PUMP 2000 GALS ACID. PUMP 4200 GALS BFRAC 20. PUMP 10000 GALS GEL
 ACID. PUMP 8000 GALS ACID. PUMP 238 BBLS TREATED WTR.
 8-15-2011 RIH WITH 1-2 7/8" SN, 1- 2 7/8" BLAST JT, 15 JTS 2 7/8" TBG, 5 1/2" X 2 7/8" TAC AND 225 JTS 2 7/8" TBG. SN @
 7549'. TAC @ 7048. ND BOP. NU WELLHEAD.
 8-17-2011 SET PUMPING UNIT. RUN ELECT SERVICE. WELL PUMPING.

Spud Date: 07/04/2011 Rig Release Date: 07/16/2011

RECEIVED

SEP 12 2011

NMOCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bev Hatfield TITLE SR. STAFF ENGR TECH DATE 09/09/2011

Type or print name BEV HATFIELD E-mail address: beverly.hatfield@apachecorp.com PHONE: 432-818-1906

For State Use Only
 APPROVED BY: [Signature] TITLE SEALING UNIT SUPERVISOR DATE SEP 19 2011
 Conditions of Approval (if any):