HOBBS OCD

	State of New Mexico		Form C-103
<u>District 1</u> Energy, Mineral 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natural (Resources 2011		WELL API NO.
DIL CONSER	OIL CONSERVATION DIVISION		30-025-32896
<u>District III</u> 1220 30u	1220 South St. Francis DECEIVED		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV Santa	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	1220 S St Francis Dr , Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		L. Van Etten	
PROPOSALS) 1. Type of Well:		8. Well Number	
Oil Well Gas Well Other		17	
2. Name of Operator			9. OGRID Number
Chevron USA Inc.			4323 10. Pool name or Wildcat
3. Address of Operator 15 Smith Rd, Midland, Tx 79705			Monument, Paddock
4. Well Location			
Unit Letter K : 1650 feet from the South line and 1650 feet from the West line			
Section 9 Township 20-S Range 37-E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: UL K Sect 9 Twp 20S Rng 37E Pit type Steel Depth to Groundwater Distance from nearest fresh water well			
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;			
feet from the South line and 1650 feet from the West line			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDO	ON \square	REMEDIAL WORK	SEQUENT REPORT OF: C
	_		
TEMPORARILY ABANDON		COMMENCE DRII	LLING OPNS DPLUG AND ABANDON PENT
PULL OR ALTER CASING MULTIPLE		CASING TEST AN	
COMPLETION		CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
or recompletion. Attach well bore only. I inhibition and the proposed completion of the proposed completion of the proposed completion.			
1. Notified EL Gonzalez w/NM-OCD on 2. Spot 150 sx "c" cmt F/5178'-3697 (Perfs) Woc tag @ 3718' Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found as 2000 which may be something as 2000 which which may be something as 2000 which which may be something as 2000 which w			
3. Displace hole w/90 bis MLF			
5. Perf & sqz. 160 sx "c" cmt from 1662'-1035' (T. Salt est./Shoe) woc tag @ 1011'			
 Perf @ 400' circ 125 sx "c" cmt down 5 1/2" up.through 8-5/8" A Install Dry Hole marker P&A complete 10-24-11 	nnullus csg to	surf. (Fr. Wtr./Surf) woc	tag @ surf
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOC	D guidelines [☐, a general permit ☐	or an (attached) alternative OCD-approved plan .
SIGNATURE ()	TITLE	Manager	DATE 10/24/11
limmy Paglay			
Type or print name Jimmy Bagley	E-mail ac	ldress:	Telephone No. 432-561-8600
(This space for State use)			
APPPROVED BY	_TITLE	TAST ME	DATE 0-3/-20/
Conditions of approval, if any:			/