

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO
30-025-21740

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
OG 1529

7. Lease Name or Unit Agreement Name:
Unit 891008492B

Antelope Ridge Unit

8. Well No. 1 G

9. Pool name or Wildcat
Delaware

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ SWD

2. Name of Operator

Citation Oil & Gas Corp.

3. Address of Operator

P O Box 690688 Houston, Texas 77269

4. Well Location

Unit Letter G: 1980 feet from the North line and 1980 feet from the East line

Section 22

Township 23S

Range 34E

NMPM

Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3425' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND
ABANDONMENT ☐

CASING TEST AND
CEMENT JOB ☐

OTHER: Repair hole in tubing ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

MIRU, RIH with 1" sinker bar on WL - tagged @4929'. POOH and RIH with string shot to 4800' - did not fire. PU power swivel and worked ASA free and POOH with tubing. Broke out 8-5/8" x 13-3/8" x-o and 5' piece of 8-5/8" casing - replaced with 5' piece of 13-3/8" casing. NU x-o over WH and BOP. RIH, stung into packer and RIH with sinker bar on sand line - tagged fill @5080' and POOH. TIH with ASA on 2-7/8" tubing and stung into packer @4953'. Pumped 9 ppg brine with RB2664 packer fluid down casing. Stung into packer with ASA and pressure tested casing to 500# - OK. ND BOP and NU WH. Landed tubing. RU pump truck and pressured up casing to 400# on chart and held for 30 mins, Bled pressure and RD pump truck. Returned well to disposal 4/5/2005.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra Harris TITLE Production/Regulatory Coordinator DATE 4/6/2005
Type or print name Debra Harris Telephone No. (281) 517-7194

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 12 2005
Conditions of approval, if any: