Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resources	Revised August 1, 2011
<u>District I</u> = (575) 393-6161 1625 N, French Dr., Hobbs, NM 88240		WELL API NO.
District JI - (575) 748-1283	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-025-23616
811 S. First St., Artesia, NM 88210 BBS 00	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	STATE L FEE X / 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aziec, NM 87410 <u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fc, NOV 1 5 2 87505	Uli Santa re, Nivi 8/303	0. State Oil & Gas Lease No.
87505		
SITNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROBOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		graph /
PROPOSALS.)		SFPRR 8. Well Number 009
I. Type of Well: Oil Well X Gas Well Other		
2. Name of Operator		9. OGRID Number
VPR Operating, LLC		10. Pool name or Wildcat
3. Address of Operator		West Sawyer (San Andres)
1406 Camp Claft Road, Stille 190, Austria, 177 707		
4. Well Location Unit Letter Y : 1980 feet from the North line and 2180 feet from the West line		
	~	NMPM Lea County
Section 28	Township 09S Range 37E 1. Elevation (Show whether DR, RKB, RT, GR, e.	
	975' GL	
5773 GC		
12 Check Apr	propriate Box to Indicate Nature of Notic	e. Report or Other Data
12. Check App		
NOTICE OF INTE	ENTION TO: SU	JBSEQUENT REPORT OF:
	PLUG AND ABANDON 🔲 REMEDIAL WO	1 /
		DRILLING OPNS. P AND A // X
PULL OR ALTER CASING N	MULTIPLE COMPL 🔲 CASING/CEME	ENT JOB
DOWNHOLE COMMINGLE		
077.150	☐ OTHER:	
OTHER:	ed operations (Clearly state all pertinent details,	and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
·		
10/24/2011 Move in rig up and attempted to unseat pump and lay down rods. Worked rods loose and started to drag out of hole. SION		
10/25/2011 Continued to laydown rods until they parted. Left rods in the tubing at 2100'. Installed BOP. Tubing was stuck. Worked		
tubing and tried to unset the anchor until tubing parted. Recovered 1181' of tubing. SION 10/26/2011 RIH and latched on to tubing with and overshot. RIH with wireline and backed off tubing at 1985'. POH with overshot and		
laid down 25 more joints of tubing. Picked up overshot, bumper sub, jars, and 6 collars. RIH to 1985 and lached on to tubing. Jared on		
tubing for 1 ½ hrs. Gained 5" and could not get anymore. Tried to release overshot. Could not release it. SION.		
10/27/2011 Attempted to release overshot again. Could not. Called wireline to back off collar below overshot. Rigged up wireline and		
backed off collar at 2017'. POH with tubing and laid down tools. SION.		
10/28/2011 RIH with 4 ½ packer and set at 1830'. Tried to pump down well. Pressured up to 500 psi. Held for 15 minutes. No drop in		
pressure. POH with packer and RIH with wireline and perf casing at 2015' RIH with packer but could not pump into perfs at 2015'.		
Released packer and spotted 25 sx class c cement on top of tubing at 2017'. WOC and tag at 1746'. Laid down remaining tubing and perforated casing at 466'. Pumped 125 sx class c cement down 4 ½ casing to perfs at 466' and up 4 ½ X 8 5/8 annulus to surface.		
10/31/2011 Rigged down unit Cut of	If well head. Filled up casing with coment to surf	face with 25 sx class c coment. Installed dry hole
marker.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
O(20)/1	,	
SIGNATURE 11/18/11/11	TITLE SQ. V. P.	DATE //-/4-//
		DATE //-14-1/ 512 COPERATING COM PHONE: 327-8776
Type or print name Robert B.	Pulle N E-mail address: beb PUPA	Openting com PHONE: 327-8776
For State Use Only	\mathcal{I}	
APPROVED BY: DATE /1-15-201		
Conditions of Approval (if any);	Approved for plugging of well bore only	ÿ.
Tomation of Approved (Intelly).	Liability under bond is received pendin	
	of C:103 (Subsequent Report of Well P which thay be found at OCD Web Page	under 2011
	Forms, www.chingdistatesiim.us/oed.	NOV 1 5 2011