Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District 1 1625 N. French Dr, Hobbs, NM 88240 HOBBS Office Pergy, Minerals and Natural Resources		WELL API NO.
District II 1301 W Grand Ave, Artesia, NM 852EB 0 8 2002L CONSERVATION DIVISION		30-025-30282
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE S
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NW 87505 Santa Fe, NW 87505		7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		HIGHTOWER A
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other SWD		8. Well Number 1
2. Name of Operator		9. OGRID Number 024010 /
V-F PETROLEUM INC.		10. Pool name or Wildcat
3. Address of Operator P.O. BOX 1889, MIDLAND, TEX	AS 79702	SHIPP, STRAWN
4. Well Location		
Unit Letter A: 571 feet from the NORTH line and 554 feet from the EAST line		
Section 4 Township 17-S Range 37-E NMPM LEA County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,778.5' RKB		
Pit or Below-grade Tank Application □ or Closure □		
Pit typeNONEDepth to Gr	oundwaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: Add perforations OTHER: LOCATE & REPAIR CASING LEAK		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
recompletion.		
11/10/11 Pull all production equipment.		
11/11/11 Set BP at 11,090'.		
11/12/11 Run tubing in hole. Release workoever rig. 12/29/11 Rig up workoever rig. Install BOP. TOH with tubing.		
12/30/11 Run packer. Locate casing leak at 9,180'.		
12/31/11 Cement through casing leak with 325 sx H 50/50 poz cement + 10% gel, 3# LCM, 3% FL & 2% CD		
followed by 665 sx H 50/50 poz + 2% gel, 3# LCM, 5% FL, & 2% CD.		
01/03/12 Run CBL. TOC by CBL 4,850'.		
I I and the second of the seco	have in the control of the host of my linearly does	ad haliaf. I further contifu that any nit an halow
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative		
OCD-approved plan		
Type or print name M. WAYNE LUNA E-mail address: Telephone No. (432) 683-3344		
(This space for State use)		
APPPROVED BY STATE STATES DATE 2-9-101		
Conditions of approval, if any:		