

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87401
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

OIL CONSERVATION DIVISION

1220 South St. Francis
Santa Fe, NM 87505

FEB 27 2012

WELL API NO. 30-025-25399
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1484
7. Lease Name or Unit Agreement Name: CITGO "LM" STATE
8. Well Number #001
9. OGRID Number 162683
10. Pool name or Wildcat LANGLIE MATIX 7 Pers-on-G
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,329' - GR
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input checked="" type="checkbox"/>
Pit type <u>STEEL</u> Depth to Groundwater _____ Distance from nearest fresh water well * _____ Distance from nearest surface water * _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbs; Construction Material * <u>NONE WITHIN 1,000'</u>

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/20/11: POOH W/ RODS; POOH W/ 2-3/8" TEG. - PARTED @ 108TH JOINT.; RIH W/ TEG. OE TO 3, 500'.
11/21/11: MIX X SQZ. INTO OPEN PERFS. @ 3,762'-3,830'A 35 SX. CMT. PLUG (PER NMOCD); WOC X TAG @ 3,320'.
11/22/11: CIRC. WELL W/ PXA MUD; MIX X PUMP A 50 SX. CMT. PLUG @ 3,180'; WOC X TAG TOP OF CMT. PLUG @ 2,660'; MIX X PUMP A 35 SX. CMT. PLUG @ 1,400'; WOC X TAG TOP OF CMT. PLUG @ 1,045'; MIX X CIRC TO SURF. A 50 SX. CMT. PLUG @ 500'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.

WELL PLUGGED AND ABANDONED 11/22/11.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under "Unknown and Unplugged"

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE David A. Eyler TITLE AGENT DATE 11/28/11

Type or print name DAVID A. EYLER

E-mail address: deyler@milagro-res.com

Telephone No. (432) 687-3033

For State Use Only

APPROVED BY [Signature] TITLE STAFF MGR DATE 2-29-2012

Conditions of Approval, if any:

FEB 29 2012