



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez
Governor

John H. Bemis
Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

07-Mar-12

HOBBS OCD

CIMAREX ENERGY CO. OF COLORADO
600 N. MARIENFELD ST SUITE 600
MIDLAND TX 79701

MAR 08 2012

RECEIVED

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

S W HARRISON No.009				K-25-24S-36E	30-025-26436-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/06/2012	Routine/Periodic	Mark Whitaker	Yes	No	6/9/2012	iMAW1206659013
Violations						
Surface Damage/Restoration						
Comments on Inspection: DO NOT RELEASE BOND. Last well on lease. Dry hole marker not correct. No lease name or well number on marker. Range is 36E not 36D. Fiberglass rods NW of marker. 3 stakes driven in ground on NW corner (flagged). Polyline on south, west and north sides of location. Polyline crosses under road to east. Drilling line or old anchor north of well NEED TO CORRECT DRY HOLE MARKER, REMOVE SUCKER RODS, STAKES, DRILLING LINE, AND ALL POLLYLINE FROM WELL SITE AND TO SALES CONNECTION. 1st notice of violation.						

MAR 08 2012

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER 015H14150977
\$0.45
03/07/12
Mailed From 88240
US POSTAGE

CIMAREX ENERGY CO. OF COLORADO
600 N. MARIENFELD ST.
SUITE 600
MIDLAND, TX 79701