Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	000000000
UNDRY NOTICES AND REPORTS ON WELLS	HOBBS C

Lease Serial No. NMLC064150 CD

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

			APR	U 5 ZUIZ			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/A	Agreement, Name and/or No	
Tymo of Woll			PE(CEIVED			
1. Type of Well ☐ Gas Well ☒ Other: INJECTION					8. Well Name and MALJAMAR C		
Name of Operator SANDRIDGE EXPL & PROD LLC E-Mail. tcallahan@linnenergy.com					9. API Well No. 30-025-0049	99-00-S1	
3a. Address 123 ROBERT S KERR AVENUE OKLAHOMA CITY, OK 73102 3b Phone N Ph: 281-8-			. (include area cod 0-4272	e)	10. Field and Pool MALJAMAR	l, or Exploratory Crayburg, SA-	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Par	ish, and State	
Sec 10 T17S R32E NENW 660FNL 1980FWL					LEA COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RE	EPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
- Notice of Intent	Acidize Dee		eepen Produc		on (Start/Resume) Water Shut-Off	
□ Notice of Intent	Alter Casing	_	ture Treat	Reclamation		✓ ☐ Well Integrity	
Subsequent Report	Casing Repair	□ New	☐ New Construction		lete	Other	
☐ Final Abandonment Notice	Change Plans	► Plug			rarily Abandon		
	Convert to Injection	□ Plug	Back	□ Water D	isposal		
2/21/2012 - MIRU PU & P&A valve. RU WL, RIH w/ 5-1/2" RD WL. RIH w/ tbg to 1600'. 2/22/2012 - Open well no prestested csg to 500#. OK. Spoof tbg, RU WL, perfed @ 222/sqz. Pressure 1200# called Espot 25 sxs, plug w/ 2% cal. too low per BLM. Break circ, 2/23/2012 - TIH w/ 15 stds. P	gauge ring to 3669'. POH v SWI & SDFN. ssure, RIH w/ tbg, tag CIBP t 25 sxs cmt. Displ TOC to 5'. RD WL. TIH w/ 5-1/2" p tLM. OK to spot plug. POC POH w/ 20 stds tbg. WOC spot 25 sxs cmt. Displ TOC	w/ gauge rir @ 3669'. (3417'. POI okr to 1830'. DH w/ pkr, T . TIH w/ tbo C to 1922'.	g. Set CIBP @ Circ hole w/ ML I, stood back 3 Load hole. Se IH w/ tbg to 22 I. Tag TOC @ POH. SDFN.	3669' as per F. Pressure 5 stds, LD reset pkr, unable 75'. Break cir 2174'. Plug w	st to c, ras.\ecepted as t	to plugging of the well be er bond is retained until tration is completed.	
	true and correct Electronic Submission #13 For SANDRIDGE tted to AFMSS for processin CALLAHAN	EXPL & PR	OD LLC, sent to AH MCKINNEY	the Hobbs	(12KMS0436SE)		
Signature (Electronic Submission)			Date 03/09/2	2012			
	THIS SPACE FOR	RFEDERA	L OR STATE	OFFICE US	E		
Approved By ACCEPTED		JAMES A AMOS TitleSUPERVISOR EPS Da		Date 04/01/2012			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to popular operations thereon.			Office Hobbs				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Additional data for EC transaction #132607 that would not fit on the form

32. Additional remarks, continued

718'. Load hole, set pkr, sqz 70 sxs cmt w/2% CAL. Displ TOC to 980', WOC. POOH w/ pkr, TIH w/ tbg, tag TOC @ 942'. POOH, LD tbg, RU WL perf @ 400', RD WL ND BOP, RIH w/ 5-1/2" pkr & 1 jt tbg. Circ. 110 sxs cmt to surface. POOH, top well off w/ cement. SDFN.

2/24/2012 - RIH w/ tbg tagged TOC @ 40'. Called BLM, Ok w/ tag. Cut off & removed WH. Top off well w/ 10 sxs cmt. RDPU, cleaned location. Set dry hole marker.