State of New Mexico Energy, Minerals and Natural Resources Department

Form C-	103
Revised	5-27-200

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1625 N French Dr , Hobbs, NM 88240 APR 2 3 2012 South St. Francis Dr. 87505	WELL API NO 30-025-07596
DISTRICT II	5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III RECEIVED	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	South Hoods (G/SA) Onti
Type of Well Other Temporarily Abandoned Other Temporarily Abandoned	8. Well No 59
2 Name of Operator Occidental Permian Ltd.	9 OGRID No 157984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	<u></u>
4 Well Location Unit Letter O 660 Feet From The South 2310 Fee	at From The East Line
Section 3 Township 19-S Range 38-E	
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3610' DF	J. S.
Pit or Below-grade Tank Application or Closure	Viiliiliiliiliiliiliiliiliiliiliiliiliil
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
Charles Assurance to Day to Indicate Nature of Natice Depart on (Othor Doto
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTURE CASING Multiple Completion CASING TEST AND CEMENT OTHER Casing integrations (Clearly state all pertinent details, and give pertinent dates	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF CASING CASING TEST AND CEMENT OTHER OTHER Casing integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the complete of th	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER OTHER Casing integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER OTHER Casing integers of Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed or Complete Operation	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request , including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO	NS. PLUG & ABANDONMENT IT JOB rity test/TA status request , including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' Top perf @4080' This Approver Abandonment	PLUG & ABANDONMENT IT JOB rity test/TA status request including estimated date of starting any completion or recompletion. All of Temporary 19 - 2014 Int Expires
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' Top perf @4080' This Approve Abandonment	PLUG & ABANDONMENT IT JOB Tity test/TA status request It including estimated date of starting any completion or recompletion. The status request including estimated date of starting any completion or recompletion. The status request including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' Top perf @4080' This Approve Abandonment I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	PLUG & ABANDONMENT IT JOB Tity test/TA status request It including estimated date of starting any completion or recompletion. The status request including estimated date of starting any completion or recompletion. The status request including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' Top perf @4080' This Approve Abandonment	PLUG & ABANDONMENT IT JOB rity test/TA status request x including estimated date of starting any completion or recompletion. All of Temporary 19 - ZO14 that any pit or below-grade tank has been/will be e OCD-approved
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' This Approve Abandonmer I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	PLUG & ABANDONMENT IT JOB Trity test/TA status request It including estimated date of starting any completion or recompletion. All of Temporary That Expires That any pit or below-grade tank has been/will be The OCD-approved Associate DATE 04/20/2012
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' Top perf @4080' This Approve Abandonmer I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative	PLUG & ABANDONMENT IT JOB Tity test/TA status request It including estimated date of starting any completion or recompletion. All of Temporary That Expires That any pit or below-grade tank has been/will be The OCD-approved Associate DATE 04/20/2012
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER Casing integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test date: 04/19/2012 Pressure readings: Initial – 563; 15 min – 540 PSI; 30 min – 538 PSI Length of test: 30 minutes Witnessed: NO Packer set @3969' This Approve Abandonmer I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	PLUG & ABANDONMENT IT JOB rity test/TA status request i, including estimated date of starting any completion or recompletion. Al of Temporary It Expires that any pit or below-grade tank has been/will be the OCD-approved Associate DATE 04/20/2012

