State of New Mexico Form C-103 Submit 1 Copy To Appropriate District Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 1625 N French Dr., Hobbs, NM 88240 WELL API NO. District II - (575) 748-1283 811 S First St, Artesia, NM 88210 HOBBS OCO CONSERVATION DIVISION 30-041-20949 5. Indicate Type of Lease <u>District III</u> - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd , Aztec, NM 874116 0 7 2012 STATE | Santa Fe, NM 87505 District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S St Francis Dr , Santa Fe, NM 87505 SUNDRY NEEDEN EAND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Proud Mary DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number Armstrong Energy Corporation 001092 3. Address of Operator 10. Pool name or Wildcat P.O. Box 1973, Roswell, NM 88202-1973 Wildcat; Fusselman 4. Well Location Unit Letter 810 feet from the South line and 1830 feet from the West line Section Township Range 34E **NMPM** Roosevelt County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: - PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **CHANGE PLANS** COMMENCE DRILLING OPNS. | | \boxtimes TEMPORARILY ABANDON P AND A MULTIPLE COMPL PULL OR ALTER CASING CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Dylan Radcliff contacted Maxey Brown with NMOCD @ 5:30 pm, Friday, August 3, 2012 and received verbal 08-04-12 approval for plugging procedure. Spot 35 sx Class "H" w/1% HR601 @ TD 8252'. Spot 35 sx Class "C" @ 7466'. Spot 35 sx Class "C" @ 6718'. Spot 60 sx Class "C" @ 3314'. Spot 70 sx Class "C" @ 2417', WOC 5 hrs, tag @ 2252' (shoe @ 2367'). Spot 32 sx Class "C" @ 1900'. Spot 30 sx Class "C" @ 450'. Spot 24 sx Class "C" from 93' to Surface. Plan to install upright Dry Hole Marker once rig moves off location. The Oil Conservation Division Must be notified 24 hours prior to the beginning of plugging operations. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. Engineer Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: 575-625-222 Conditions of Approval (if any):