Sι	Jbm	hit 3	Co	pies	
to	Ap	рго	pria	te	
			Sec	_	

F.

State of New Mexico Energy, Minerals and Natural Resources Department

		1			
OIL CONSERVATION DIVISION			WELL API NO. 30-025-36228		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	2040 South Pacheco		5. Indicate	Type of Lease	
1.0. Drawer DD, Artesia, Wir 66210	Santa Fe	Santa Fe, NM 87505		STATE 🗌 FEE	
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil	& Gas Lease No.	
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERV	S AND REPORTS ON WE OSALS TO DRILL OR TO DI OIR. USE "APPLICATION FO ORM C-101) FOR SUCH PR	EEPEN OR PLUG BACK TO A OR PERMIT"	7. Lease N	Name or Unit Agreement Na	me
I. Type of Well: OIL GAS WELL WELL	OTHER			Grizzell 'B'	
2. Name of Operator	Zia Energy, Inc.		8. Well No.	5	
3. Address of Operator		· · · · · ·	9. Pool nan	ne or Wildcat	
PO Box 2	2510, Hobbs, NM 8824	41	Eun	ice San Andres Southwest	
4. Well Location Unit Letter <u>H</u> <u>1980</u> Feet Fro	om The North Line	and 810 Feet F	rom The East	Line	
Section 8 Townshi	ip 22S Rang	z 37E NMPI	M Lea	County	
		hether DF, RKB, RT, GR, etc			
11. Check Appr NOTICE OF INTENTION 1		ature of Notice, Report, or Ot SUBSEQ	her Data UENT REPO	DRT OF:	
	LUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	HANGE PLANS	COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CEMENT J	ов 🛛		
OTHER:		OTHER:			
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	ations (Clearly state all pertir	nent details, and give pertinent dat	tes, including es	timated date of starting any prop	osed
4/26/03 Spud 12 1/4" hole.					
4/27 27 TD 1166'. RIH with g	guide shoe, shoe joint	t with centralizer and flo	at collar. R	TH with remaining 23 i	ts of
8 5/8" 24# casing, set casing					
Premium Plus with .25 #/sx fl					
Calcium Chloride (1.34 ft3/sx)		. ,			
4/28 Drill out shoe and test ca					
5/2 TD 4290'. RIH with 5 1/2"	15.50# J-55 casing.	Set casing @ 4290'. RU	J Halliburto	on. Pump 24 htt getted	
fresh water sweep. Pump 475	sxs Light Premium P	Plus with .25 lbm/sx floc	ele, 5 lbm/s	sx salt, 200 LAP-1 (100	8
fluid loss control) (2.04 ft3/sx)). Tail in with 500 sx	Premium Plus 50/50 Po	z with .4%	LAP/h/1.5 lbm/sx	12
Potassium Choride, .25 lbm/sx	flocele, .25 lbm/sx I	D-AIR (defoamer), .3%	CFR-3 (Dis	persant), (1.29, ft3/sx).	14
Circulate 132 sxs.				6	324
				100 4 VA 3	122324 25
I hereby certify that the Information above is true and c	complete to the best of my knowledge	and belief.		UP CONTRACTOR	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
SIGNATURE	\sim	TITLE Engineer		DATE 521,2/03 . 61	36/

Scot repor Scott Nelson TYPE OR PRINT NAME 505-393-2937 TELEPHONE NO. (This space for State Use) PETROLEUM ENGINEER JUN 2 4 2003 APPROVED BY DATE ald Alla CONDITIONS OF APPROVAL, IF ANY: