Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-08710
Oil CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Eunice Monument South Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Dance Monament South Ont
PROPOSALS.)	8. Well Number 399
Type of Well: Oil Well X Gas Well Other Name of Operator	9. OGRID Number 005380
XTO ENERGY INC.	9. OGRID Number 003300
3. Address of Operator 200 LORAINE	10. Pool name or Wildcat
MIDLAND, TX 79701	Eunice Monument Grayburg-San Andres
4. Well Location	
Unit Letter K 1980 feet from the SOUTH line and 1980 feet from the WEST line	
Section 15 Township 21 S Range 36 E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
The Biological States of the S	
Pit or Below-grade Tank Application or Closure	Participate angular and an angular ang
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR	П и терии о о о о и о и о
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
	_
OTHER: OTHER: OTHER: OTHER:	d give portinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	men wendere diagram of proposed completion
1	
7/1/05 MIRU, NDWH, NU BOP, TAGGED CMT @3641'. DRLG CIBP, PUS	HED TO BTM @2847'.
7/6/05 thru 7/8/05 SWBD	
7/12/05 ACD Grayburg perfs 3762-3950' w/4000 gals 15% NEFE HCL & 3000#	
ISIP = 413 psig, Max/Min press = 1353/470 psig. 177 BLWTR. RDM	
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	133
The beautiful death in Countries to the state of the stat	11 11 0
I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	e and belief. I further certify that any pit or below-
In I have	or an (attended) and many to GCD approved plan
SIGNATURE // July TITLE: PRODUCTION ANAL	<u>YST</u> DATE: <u>08-03-2005</u>
Toma an anima areas Marris Mar	m 1 1 22 22 22 22 22
Type or print name Mary Lyn Marr E-mail address: MaryLyn Marr@xtoenergy.c	<u> </u>
APPROVED BY: Jay W. Wills JEFFELD REPRESENTATIVE !!/STAFF MANAGER DATE: 1 5 2005	
APPROVED BY: Law W. WILL THEFT D REPRESENTATIVE	DATE 4
Conditions of Approval (if any):	DAUG 1 5 2005
U	