

Submit 1 Copy To Appropriate District

Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

HOBBS OCD

OIL CONSERVATION DIVISION

DEC 07 2012

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-25365

5. Indicate Type of Lease

STATE ☒ FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

WEST PEARL QUEEN UNIT

8. Well Number #169

9. OGRID Number

25482

10. Pool name or Wildcat

PEARL QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

STATE OF NEW MEXICO formerly Xeric Oil & Gas Corp

3. Address of Operator

1625 N. French Drive Hobbs, NM 88240

4. Well Location

Unit Letter N : 1305 feet from the S line and 2565 feet from the W line

Section 28

Township 19S

Range 35E

NMPM

County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


SEE ATTACHED P&A PROCEDURE

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



Title COMPLIANCE OFFICER

DATE 12/07/2012

Type or print name MARK WHITAKER

E-mail address: Marka.Whitaker@state.nm.us

PHONE: 575-393-6161

For State Use Only

PPROVED

BY:  TITLE

DATE

Conditions of Approval (if any):

State of New Mexico formerly Xeric Oil & Gas Corp
West Pearl Queen Unit No. 169

Set CIBP at 4650' and cap w/ 25 sx cmt. Pressure test csg.

Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls.

Spot 30 sx cmt at 3300'.

Spot 25 sx cmt at 1850'. WOC and Tag.

Spot cmt from 250' to surface.

Cut off wellhead and install dry hole marker.

