

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
HOBBS OCD
 OIL CONSERVATION DIVISION
 AUG 26 2013
 220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-00828
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Celero Energy II, LP		6. State Oil & Gas Lease No.
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701		7. Lease Name or Unit Agreement Name Rock Queen Unit
4. Well Location Unit Letter <u>B</u> : <u>660</u> feet from the <u>N</u> line and <u>1980</u> feet from the <u>E</u> line Section <u>23</u> Township <u>13S</u> Range <u>31E</u> NMPM County <u>Chaves</u>		8. Well Number <u>12</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <u>247128</u>
10. Pool name or Wildcat Caprock; Queen		

12. Check Appropriate and Indicate Nature of Notice, Report or Other Data

NOTICE OF TEMPORARY PLUGGING Approved for Plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Specifically for Subsequent Report of Well Plugging) which may be found at OCD web page under forms/ www.emnrd.state.nm.us/oed	<input type="checkbox"/>	SUBSEQUENT REPORT OF:	
	<input type="checkbox"/>	<input type="checkbox"/> REMEDIAL WORK	<input type="checkbox"/> ALTERING CASING
	<input type="checkbox"/>	<input type="checkbox"/> COMMENCE DRILLING OPNS.	<input checked="" type="checkbox"/> P AND A
	<input type="checkbox"/>	<input type="checkbox"/> CASING/CEMENT JOB	<input type="checkbox"/> OTHER:

7/26/13 - NDWH & NUBOP. RIH w/ CIBP & set @ 2808'. TIH w/ 90 jts tbg, spot 25 sx Class "C" cmt w/ 2% CACL, displace w/ 8.5 bbls. TOH & WOC.

7/30/13 - TIH & tag @ 2427'. Circ mud to 2300'. RIH w/ csg gun & shoot 4 SPF @ 2300'. Started out w/ WL & well came in. SWI w/ 800' of WL in hole. Blew well down. Open BOP & remove WL. Recovered all. PU pkr & TIH to 1928', load hole & set pkr.

7/31/13 - Set pkr. Could not establish inj rate. TOH w/ pkr. TIH OE to 2363'. Work on pump until noon. Circ mud, but had weak circ & holding 1000# on tbg. Tried to reverse out, but w/ same results. TOH & rabbit tbg back in hole. Found no plug. Still had weak circ. TOH & PU 3 3/8" bit & BS. TIH to 1800' & had same results. TOH. RIH & shoot 4 SPF @ 1463'.

8/1/13 - TIH OE to 622', break circ, full returns w/ 300#. Continue TOH to 2363', check circ, full returns @ 400#. Spot 30 sx Class "C" cmt neat. Cementer forgot to add CACL. TOH & WOC. Check sample, still soft. PU AD-1 pkr. TIH to 1493'. Pressured up on plug to 400#, did not hold. Pushed down approx. 90'. * Continued on attached sheet

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lisa Hunt TITLE Regulatory Analyst DATE 08/21/2013

Type or print name Lisa Hunt E-mail address: lhunt@celeroenergy.com PHONE: (432)686-1883

For State Use Only
 APPROVED BY: [Signature] TITLE Dist. Mgr DATE 8-28-2013
 Conditions of Approval (if any):

Rock Queen Unit #12 – C103 continued

8/2/13 - Test plug to 500#, ok. Unseat pkr, TOH, PU PS & BP. TIH & tag @ 2118'. TOH & PU AD-1 pkr. TIH to 1119', could not establish inj rate. TOH w/ pkr. TIH w/ PS & BP to 1523'. Supposed to pump 30 sx plug, but cementer pumped 40 sx Class "C" cmt w/ 2% CACL, displaced w/ 3 bbls & plugged PS. TOH w/ wet string, 4 bbls cmt in tbg.

8/5/13 - TIH clearing cmt plugs out of tbg. Tag @ 1182'. Raise tbg to 404' & attempt to establish circ on 7 5/8" x 4 1/2", unable to circ. Raise tbg to 217'. RIH w/ 1 9/16" gun through tbg & shoot 4 SPF @ 363' TIH OE to 404', establish circ on 7 5/8" x 4 1/2" & fill both sides to surface w/ 250 sx Class "C" w/ 2% CACL. LD tbg & NDBOP. Csg full.

8/6/13 - Dig out WH's & set marker. Well now P&A'd.
