Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 HOBBS Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II (575) 748 1282	30-025-41361
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460 Santa Fe, NM 87505	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM RECEIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	VB-2294
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Gramma 27 State
PROPOSALS.)	8. Well Number 1 H
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
Caza Operating, LLC	249099 249099
3. Address of Operator	10. Pool name or Wildcat
200 North Loraine, Suite 1550, Midland, Texas 79701	Grama Ridge; Bone Spring NE 28435
4. Well Location	
Unit Letter O: 330 feet from the South line and 1980 feet from the East line	
Township 21'S Range 34 E	NMPM County
11. Elevation (Show whether DR, RKB, RT, GR, etc.).	A second
3682 ft GR	
and the control of th	Little only grant curse
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	en e
CLOSED-LOOP SYSTEM'	
OTHER: OTHER: Perform	n perf plug fracture stimulation
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	npletions: Attach wellbore diagram of
proposed completion of recompletion.	
5-8-14_Perform Toe prep on perfs 15,369-72, 15,271-74, 15,173-76 (48 holes) .4" E	HD with 3000 gals 15% HCL NEFE.
5-(13-17)-14_ Perform perf & plug fracture stimulation on perfs 15,372- 11,351 (672 holes) w/ total 54,500 gals 15% HCL	
NEFE acid +329,900 lbs 30/50 Carbo Prop + 2,936,320 lbs 20/40 Pro	Lite.
5-18-14_ Clean out well bore to PBTD 15,399 ft.	
5-19-14_ Started flow back @ 06:30 hrs CDT 5-19-14.	
of the file started from back (@ sociot file object to the file)	
	•
Spud Date: 3/20/2014 Rig Release Date: 5/3/2014	
	<u> </u>
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
SIGNATURE SIGNATURE Operations Manager	DATE
SIGNATURE TITLE Operations Manager	DATE
Type or print name Richard L. Wright E-mail address: rwright@cazap	PHONE: 432 682 7424
For State Use Only	
Petroleum Engineer	
APPROVED BY: DATE DATE	
Conditions of Approval (if any).	DATE DATE