Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-05650
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE  FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Saina 1 6, 14141 67505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTIC	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Monument G/SA Unit Blk. 5
1. Type of Well: Oil Well	Gas Well I Injection well $\hat{u}_{\bullet}$ .	8. Well Number 11
2. Name of Operator	Gas Well Injection well MAP 23	9. OGRID Number 873
Apache Corp.	~ * * * * * * * * * * * * * * * * * * *	3. OSKID Hamoer 073
3. Address of Operator	Pro 13	10. Pool name or Wildcat
P O box Drawer D Monument NM	88265	Eunice Monument G/SA
4. Well Location		
	1000 6 (6 (1 6 1)	1000
Unit LetterK:	1980 feet from the S line and	1980feet from the
Wline		
Section 19	Township 19S Range 37I	E NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	<del></del>	The Samueleten street and the street
12 Chack A	ppropriate Box to Indicate Nature of Notice	Papart or Other Data
12. Check A	ppropriate box to indicate Nature of Notice	e, Report of Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING		
TEMPORARILY ABANDON	<del></del>	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEI	NT JOB 📙
DOWNHOLE COMMINGLE		
OTHER: MPT	OTHER:	
	eted operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
	rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	
proposed completion or reco		ompletions. Attach wellbore diagram of
proposed completion of rece	impletion.	
	•	
Plan to mayo in a numn truck Process	are test the casing to 500 psi and chart the pressure fo	= 22 minutes
rian to move in a pump truck. Fressu	Te test the casing to 500 psi and chart the pressure to	of 32 minutes.
<b>:</b>		
	<del></del>	
Spud Date:		
Space Bate.	Rig Release Date:	
	Rig Release Date:	
	Rig Release Date:	
I hereby certify that the information a	Rig Release Date:	dge and belief.
I hereby certify that the information a	above is true and complete to the best of my knowled	
$\alpha$ )sm	above is true and complete to the best of my knowled	
I hereby certify that the information a	above is true and complete to the best of my knowled	
SIGNATURE SIGNATURE	above is true and complete to the best of my knowled	
SIGNATUREJim Ellison	above is true and complete to the best of my knowled	
SIGNATURE SIGNATURE	above is true and complete to the best of my knowled	DATE 3-23-/5  pacheccorp.com_ PHONE: 575-44/-7734
SIGNATUREJim Ellison For State Use Only	TITLEInstrument Tech E-mail address: _JD.Ellison@a	DATE <u>3-23-15</u> pacheccorp.com_PHONE: <u>575-441-77</u> 34
SIGNATUREJim Ellison For State Use Only  APPROVED BY: Bullou	TITLEInstrument Tech E-mail address: _JD.Ellison@a	DATE <u>3-23-15</u> pacheccorp.com_PHONE: <u>575-441-77</u> 34
SIGNATUREJim Ellison For State Use Only	TITLEInstrument Tech E-mail address: _JD.Ellison@a	

APR 0 2 2015 L