

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-20251
5. Indicate Type of Lease STATE ☒ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Meyers
8. Well Number 1
9. OGRID Number 2306D1
10. Pool name or Wildcat Lovington-Paddock
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
J M Cox Resources, LP

3. Address of Operator
PO Box 2217, Midland, TX 79702

4. Well Location
Unit Letter **E** : **1980** feet from the **N** line and **660** feet from the **W** line
Section **33** Township **16S** Range **37E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		E-PERMITTING <SWD INJECTION>	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REN ☐	CONVERSION ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	CON ☐	RETURN TO ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CAS ☐	CSNG ☐
DOWNHOLE COMMINGLE ☐			CHG LOC ☐
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU plugging equipment.

2. Set 5 1/2 CIBP @ 6150. Circulate hole w/ mud laden fluid & spot 25 sx cement on top.

3. Perf & Sqz 45 sx @ 2400-2300.

4. Perf & Sqz 150 sx @ 415' to surface.

5. Cut off well head and weld on Dry Hole Marker.

SPOT 25 SXS CMT @ 4738.

SPOT 25 SXS CMT @ 3050.

Perf & SQZ 25 SXS CMT @ 2050. WOC: TAG

The Oil Conservation Division

MUST BE NOTIFIED 24 Hours

Prior to the beginning of operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 6-3-15

Type or print name Ben Montgomery E-mail address: ben@benandassociates.com PHONE: 932-580-7161

For State Use Only

APPROVED BY: Maelys Brown TITLE Dist. Supervisor DATE 6/3/2015

Conditions of Approval (if any):

JUN 08 2015


MB

J. M. Cox Resources, LP

Meyers #1


30-025-20251

Perf: Sg2 150 ST @
415' to surface.




8 5/8" 365' 300 ST

Perf: Sg2 45 ST @
2400 - 2300



TOC 2443

CIBP@ 6150' w/ 20 ST



Perf: 6164 - 6230

5 7/8" 6300' 1000 ST @
TOC 2440 calc.