Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103	
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. 1200 South St. Francis Dr.		30-025-32297 5. Indicate Type of Lease	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOS/ DIFFERENT RESERVOIR. USE "APPLIC/	7. Lease Name or Unit Agreement Name		
PROPOSALS.)	Quarry		
1. Type of Well: Oil Well X G	8. Well Number 001		
2. Name of Operator	E & D C	9. OGRID Number	
State of New Mexico formerly Cany 3. Address of Operator	10. Pool name or Wildcat		
1625 N. French Drive Hobbs, 1	Bowers, 7 Rivers		
4. Well Location			
Unit LetterL:	_1980feet from theSouth line and	890feet from theWestline	
Section 19	Township 18S Range 38E		
	11. Elevation (Show whether DR, RKB, RT, GR, e	rtc.)	
12. Check Aj	ppropriate Box to Indicate Nature of Notic	e, Report or Other Data	
E-PERMITTING <swd< td=""><td>INJECTION> SU</td><td>JBSEQUENT REPORT OF:</td></swd<>	INJECTION> SU	JBSEQUENT REPORT OF:	
PE CONVERSION	RBDMS REMEDIAL WO	ORK ALTERING CASING	
TE RETURN TO			
PI CSNGENVIRO	CHG LOC CASING/CEME	ENT JOB	
INT TO PA P&A N	A R		
OTHER:	OTHER:		
	eted operations. (Clearly state all pertinent details, k). SEE RULE 19.15.7.14 NMAC. For Multiple (mpletion.		
		HOPPECOOP	
	See Attatched	HOBBSOCD	
	NOV 1 0 0015		
NOV 1 2 2015			
		RECEIVED	
I hereby certify that the information al	bove is true and complete to the best of my knowle	dge and belief.	
SIGNATURE	TITLE	DATE	
SIGNATORE	IIILE	DATE	
Type or print name	E-mail address:	PHONE:	
APPROVED BY:	Brown TITLE Dist. Sup	DENVISOL DATE 11/12/2015	
Conditions of Approval (if any):		,	
	N	OV 1 8 2015	
	14	10/119	

V	OV	1	8	20	15

Plugging Report

5/8/2015 MIRU. Worked pump free and laid down 129 ¾" rods. Moved remaining equipment to location.

5/11/2015 Dug out cellar and installed BOP. POOH with tubing and tally. Picked up scrapper and RIH to 3190'. POOH with scrapper. Picked up 5 ½" CIBP and set at 3158'. Circulated MLF and tested casing to 500 psi. Held Good. Spotted 55 sx class c cement on CIBP. Stood back 25 stands and laid down 52 joints on the ground. 102 total joints of 2 3/8" tubing in the well.

5/12/2015 Perforated 5 ½" casing at 1500'. RIH and set packer at 1211'. Pressured up to 750#. Bled off and pressured up to 900#. Held 15 minutes. Not drop in pressure. Released packer and POOH. RIH open ended to 1558' and spotted 35 sx cement with CaCl. POOH 15 stands and closed BOP. Loaded casing and pressured up to 500# with 2 bbls. WOC 3 hrs and tagged at 1269'. Laid down tubing and perforated 5 ½" casing at 368'. Established circulation and pumped cement down 5 ½" casing to perfs at 368' and up annulus to surface. Took 115 sx.

5/13/2015 Rigged down. Cut off wellhead. Cement was to surface on both strings. Installed marker and cut off anchors. Installed guard rail around marker and painted yellow. Cleaned pit.