

Submit 1 Copy To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 October 13, 2009

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-38317
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Monument G/SA Unit Blk. 10
8. Well Number 363
9. OGRID Number 873
10. Pool name or Wildcat Eunice Monument G/SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM G-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well

2. Name of Operator
Apache Corp.

3. Address of Operator
P O box Drawer D Monument NM 88265

4. Well Location
 Unit Letter I : 2630 feet from the S line and 130 feet from the E line
 Section 30 Township 19S Range 37E NMPM Lea County

HOBBS OCD
 NOV 12 2015
 RECEIVED

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING <SWD INJECTION> P CONVERSION _____ RBDMS <u>MB</u> T RETURN TO _____ TA <u>TA</u> P CSNG _____ ENVIRO _____ CHG LOC _____] D INT TO PA _____ P&A NR _____ P&A R _____ OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: TA well bore <input checked="" type="checkbox"/>
---	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 3668-3948

Move in a pulling unit. Set a CIBP 3620' with 35' of cement on top. Load the casing with packer fluid & Test to 515 psi for 30 minutes & chart the results. A slight gain in pressure to 518#. Apache Corporation requests a TA status for this well.

This Approval of Temporary Abandonment Expires 11/10/2020

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Instrument Tech DATE 11/10/15
 Type or print name Jim Ellison E-mail address: JD.Ellison@apacheccorp.com PHONE: 575-441-7734
For State Use Only
 APPROVED BY: [Signature] TITLE Dist Supervisor DATE 11/12/2015
 Conditions of Approval (if any): NOV 18 2015

PRINTED IN U.S.A.

Pump # 2 TRH
Paul King
Apache Corp. # 363
NM GSAV
30-025-38317
Good Luck

NOV 1 2005
RECEIVED

DATE 11-10-15
BR 2221




NOON

6 PM

MIDNIGHT

6 AM

AMERICAN VALVE & METER
CALIBRATED 8-14-15
S.N. 1432



585 #

515 #