Submit 3 Copies To Appropriate District Office	State of New Me	xico	Form C-103	
District I	Energy, Minerals and Natu	ral Resources	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240 District II	•		WELL API NO. 30-025-28683	
1301 W. Grand Avc., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran	ncis Dr.	STATE TEE	
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			32 447	
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLI	JG BACK TO A		
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FO	OR SUCH	Seven Rivers Queen Unit	
1	Gas Well  Other		8. Well Number #6 Z	
2 Name of Operator .	0 -		9. OGRID Number	
Arong	Resources Inc.		2 204 20	
3. Address of Operator	·/ · · · · · · · · · · · · · · · · · ·	•	10. Pool name or Wildcat	
49 20 SLCWX, S	vita 102 Tulsa, OR	74105	Seven River Queen	
4. Well Location	1505 Car South	ta 2: 1 2	1120 0 10 11 14 10 11	
			480 feet from the Wast line	
Section 3 4	Township 225 Ra		NMPM Leg County	
<b>医数数数据 电电影形式</b>	11. Elevation (Show whether DR, 3 499	RKB, RT, GB, etc.)	The profit is the least of the	
Pit or Below-grade Tank Application 🔲 o		<u> </u>		
Pit type Depth to Groundw		ater well Dist	ance from nearest surface water	
Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material	
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. P AND A	
DULL OD ALTED CACING TO	MULTIPLE COMPL	CASING/CEMENT	TJOB 🗆	
PULL OR ALTER CASING				
e e			<b>+</b> 4	
OTHER:		OTHER:	TA	
OTHER:  13. Describe proposed or comp	leted operations. (Clearly state all )	OTHER:	T A   d give pertinent dates, including estimated date	
OTHER:  13. Describe proposed or comp of starting any proposed we	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	T A   d give pertinent dates, including estimated date	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:  VCUIATC PACKET FILE  13.14.15.15.15.15.15.15.15.15.15.15.15.15.15.	
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'	OTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:	
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'  of Temporary 3/28/1, Expires	OTHER: Descripent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion; vculate Packer Flu	
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-50'-3784'  of Temporary 3/28/1, Expires	OTHER: Destrinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion; vculate Packer Flu	
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multipork). SEE RULE 1103. For Multipork 3 5 7 6' 0 1 1 5 0' - 3 7 8 4'  of Temporary 3/28/1/2 Expires 3/28/1/2	oTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:  year of the Packer Floring and belief. I further certify that any pit or below-or an (attached) alternative OCD-approved plan	
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multipork). SEE RULE 1103. For Multipork 3 5 7 6' 0 1 1 5 0' - 3 7 8 4'  of Temporary 3/28/1/2 Expires 3/28/1/2	oTHER: pertinent details, and le Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion; $VCUIATCPACKCPIC$ e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan $\square$ .  Supervisor DATE 3-2 P-06	; d.
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 34  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Dany	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-  50'-3784'  of Temporary 3/28/1/2  Expires	oTHER: pertinent details, and le Completions: At 26-06 c	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion; $VCUIATCPACKCPIC$ e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan $\square$ .  Supervisor DATE 3-2 P-06	; d.
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Danny	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-  50'-3784'  of Temporary 3/28/1/2  Expires	oTHER: pertinent details, and le Completions: At 26-06 c	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion; $VCUIATCPACKCPIC$ e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan $\square$ .  Supervisor DATE 3-2 P-06	; d.
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 34  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Dany	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-  50'-3784'  of Temporary 3/28/1/2  Expires	oTHER: pertinent details, and le Completions: At 26-06 c	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion:  year of the Packer Floring and belief. I further certify that any pit or below-or an (attached) alternative OCD-approved plan	; d.
OTHER:  13. Describe proposed or composed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Danny  Type or print name Danny  For State Use Only  APPROVED BY: Haur 14	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-  50'-3784'  of Temporary 3/28/1/2  Expires	oTHER: pertinent details, and le Completions: At 26-06 c	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Free and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  Supervisor DATE 3-28-06  Telephone No. 505-63/	; d.
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Set CIBP  Perfs 36  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name  For State Use Only	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multip at 3576' on 1-  50'-3784'  of Temporary 3/28/1/2  Expires	oTHER: pertinent details, and le Completions: At  26-06  est of my knowledg  a general permit  oduction  ddress:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Free and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  Supervisor DATE 3-28-06  Telephone No. 505-63/	; d.

