

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31783
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	19
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3997'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>G</u> : <u>1501</u> Feet From The <u>NORTH</u> Line and <u>1620</u> Feet From The <u>EAST</u> Line Section <u>25</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3997'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TAD INJ TO PRODUCER ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-13-06: MIRU. TIH W/BIT. TAG CIBP @ 5975. DRILL CIBP 5975-5977 & PUSH TO 6070. LD 2 JTS 2 7/8" TBG TO 6007. WASH TO BTM @ 6313.
4-14-06: TIH W/2 JTS 2 7/8" TBG. TAG FILL @ 6070. WASH FILL FR 6070-6209.
4-17-06: TIH W/RBP & 193 JTS TBG SUB. TEST CSG TO 500#. GOOD. TIH W/CCL/CBL/GRL TOOLS. TAG RBP @ 6018. LOG FR 6018-4700.
4-18-06: TIH W/RETR HEAD TO 6030. LATCH ONTO RBP & TOH. TIH W/PKR TO 6030. SET PKR @ 6030. TIH W/CMT RET & SET @ 6022. TIH W/CMT RET STINGER & 193 JTS 2 7/8" TBG. PMP 200 SX CL H CMT THRU RET @ 6022. STING INTO RET. PMP 200 SX CMT 42 BBLs DN TBG. PMP 24 BBLs DISPLACEMENT. REV OUT 10 BBLs CMT.
4-19-06: PERF 5981-5983, 5991-6001, 5951-61, 5968-5978. TIH W/PKR, SN, WS TO 5890. SET PKR @ 5890.
4-20-06: ACIDIZE GLORIETA PERFS 5951-6001 W/4000 GALS 15% ACID. RU SWAB.
4-21-06: SWAB.
4-24-06: REL PKR. MOVE IN 193 JTS 2 7/8" PROD TBG. PU MJ, PERF SUB, SN, TBG SUB, TAC, TAC @ 5822. SN @ 5920. BOT @ 5954.
4-25-06: SET TAC. MOVE IN RODS. PU GAS ANCHOR & RODS. SPACE OUT 43".
4-26-06: RIG DOWN. FINAL REPORT. WAIT ON COMPLETION TEST.

5-13-06: ON 24 HR OPT. PUMPING 1 OIL, 3 GAS, & 628 WATER.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 5/23/2006

TYPE OR PRINT NAME Denise Pinkerton

Telephone No. 432-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE

JUN 13 2006

DeSoto/Nichols 12-93 ver 1.0