Submit 3 Copies To Appropriate District	State of New	Mexico	\mathbf{F}	orm C-103
Office District I	Energy, Minerals and I	Natural Resource	es	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		A	WELL API NO.	
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION		30-005-27945		
1301 W. Grand Ave., Artesia, NM 88210 District III	District III 1220 South St. Francisc Dr.		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, Natectived		6. State Oil & Gas Lease No.		
District IV	Sama PC, 19		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		Hobbs		
SUNDRY NOTION	CES AND REPORTS ON WE	ELL GED	7. Lease Name or Unit Agreer	nent Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN O	R PLUG BACK TO A	Hominy "36" State	
DIFFERENT RESERVOIR. USE "APPLIC	ATION FOR PERMIT" (FORM C-10	01) FOR SUCH		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 1	
2. Name of Operator	Gas Well Galer		9. OGRID Number	
Pogo Producing Company	OOM	IDENTIAL	017891	
3. Address of Operator		-1171-N HAI	10. Pool name or Wildcat	
P. O. Box 10340, Midland, TX 797	702-7340	1 4 7 1 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Wildcat	
4. Well Location				
.,	CO Seat from the Court	line and 22	10 fact from the East	line
	660 feet from the South			
Section 36	Township 15S	Range 31I	The state of the s	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
Pit or Below-grade Tank Application or Closure				
Pit typeDepth to Groundwa	aterDistance from nearest f			
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bb	ls; Construction Material	
12. Check A	Appropriate Box to Indica	te Nature of No	otice, Report or Other Data	
				_
			SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				CASING 🗆
TEMPORARILY ABANDON	CHANGE PLANS		E DRILLING OPNS. X P AND A	Ш
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CI	EMENT JOB	
	[OTUED.		m
OTHER:	leted operations (Clearly stat	OTHER:	ils and give pertinent dates including	estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
of recompletion.				
Spud & Set Surface Csg - MIRU Par	tterson #629. Spud well @ 17	2:30 hrs 04/12/06.	Drld 17-1/2" hole to 809'. TD reached	d @ 02:00 hrs
04/15/06. Ran 20 its 13-3/8" 48# H-40 csg. Cmt'd w/ 750 sks 35:65 POZ C @ 12.8 ppg followed by 250 sks Cl C + 2% CaCl2 @ 14.8				
ppg. Plug down @ 20:00 hrs 04/15/06. Circ 187 sks to surface. WOC 24 hrs. Make cut-off. Weld on WH. NU BOP. Test BOP & csg				
to 1200# for 30 mins ok.				
Intermediate Csg – Drld 12-1/4" hold	e to 4480'. TD reached @ 08:	:00 hrs 04/26/06.	Ran 97 jts 9-5/8" 43.5# N-80 csg. Cmt	w/ 1900 sks
35:65 POZ C @ 12.4 ppg followed by 200 sks Cl C + 2% CaCl2 @ 14.8 ppg. Ran temp survey. TOC @ 410'. WOC 24 hrs. Make cut-				
off. NU BOP & test to 2000# for 30	mins ok. Test csg to 2000# for	or 30 mins ok.		
	5 5 (0) 1 1 . 14 100) TD	1 10 14 451	0.00 0.00 I are al mell and IXalliham	ton Don 250
TD & Production Csg – Drld 8-1/2"	-7-7/8" hole to 14,100". 1D	reacned @ 14:45	hrs 06/18/06. Logged well w/ Hallibur d stage w/ 1250 sks POZ C + add. Circ	ion. Kan 330
jts 5-1/2" 1/# P-110 L1&C csg. Cm	25.65.6 POZ C followed by	C + add. Clift u 2 200 eks C Neat C	Fire 285 sks to surface. Test csg to 300	0# for 30 mins
ok. Ran CBL 07/07/06.	33.03.0 FOZ C followed by 2	200 SKS C INCAL. C	and 200 sks to surface. Test esg to 300	O# 101 50 IIIII13
or. Rail CDL 07/07/00.				
			•	
I haraby cartify that the information	above is true and complete to	the hest of my kno	owledge and belief. I further certify that	ny nit or below-
grade tank has been/will be constructed or	above is true and complete to	lines \square , a general pe	rmit or an (attached) alternative OCD-ap	in, pit of below
No.11 111	closed according to NMOCD guide			oroved plan ∐.
	. / ,			oroved plan ∐.
SIGNATURE (SAME)	. / ,	LE Sr. Eng Tech		oroved plan ∐.
	type TITI	LE <u>Sr. Eng Tech</u>	DATE <u>01/18/07</u>	oroved plan ∐.
Type or print name Cathy Wright	type TITI	E Sr. Eng Tech	DATE <u>01/18/07</u> n Telephone No. 432-685-8100	oroved plan ∐.
Type or print name Cathy Wright For State Use Only	E-mail address: wrightc@p	LE <u>Sr. Eng Tech</u>	DATE <u>01/18/07</u> n Telephone No. 432-685-8100	oroved plan ∐.
Type or print name Cathy Wright For State Use Only	E-mail address: wrightc@p	LE <u>Sr. Eng Tech</u>	DATE <u>01/18/07</u> n Telephone No. 432-685-8100	
Type or print name Cathy Wright For State Use Only	type TITI	LE <u>Sr. Eng Tech</u>	DATE <u>01/18/07</u> n Telephone No. 432-685-8100	