Form 3160-5 (April 2004)

UNITED STATES OCD-IDEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOBBS

ERIOR

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No.	
LC-030187	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit o	_				
1. Type of Well Gas Well Other				8. Well Na	_			
2. Name of Operator	ducing Company			9. APIW	Lamunyon #88	_		
Pogo Producing Company a Address 3b. Phone No. (include area code)			e area code)	30-02				
P.O. Box 10340, Midlan	432-685-8100		10. Field an					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Langl	_Grayburg				
				11. County	or Parish, State			
1980' FNL & 990' FEL, Section 21, T23S, R37E			Lea Co	_				
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OF	R OTHER DATA	_		
TYPE OF SUBMISSION		TYI	PE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Sta	art/Resume)	Water Shut-Off Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete		× Other spud			
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily Al Water Disposal			- 		
13. Describe Proposed or Complete	ed Operation (clearly state all perti	nent details, including esti	mated starting date of a	ny proposed we	ork and approximate duration thereof.	_		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud & Set Surface Csg – MIRU Capstar #23. Spud well @ 06:00 hrs 03/03/07. Drld 12-1/4" hole to 1140'. TD reached @ 12:00 hrs 03/04/07. Ran 27 jts 8-5/8" 24# J-55 csg. Cmt'd w/ 800 sks Cl "C" + 2% CaCl2. Plug down @ 18:00 hrs 03/04/07. Circ 150 sks to surface. WOC 14 hrs. Make cut-off. Weld on WH. NU BOP's & test to 1000#. Test csg to 1000# for 30 mins ok.

				282728	293037		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	l			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	\$1000	25	
Cathy Wright	Title	Sr∙ Eng	Tech	23	11904	6	
Signature Collow White	Date	03/12/	07	27.22	COR	£6.	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE THE POR RELOCATION							
Approved by		Title	ACUI T	Date	ar er Arey	\top	
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.		Office		MAR 1	5		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter (Instructions on page 2)	person r within	knowingly and willfuits jurisdiction.	illy to mal	FREDER	HEDROWNERS AFTER	United	
(Instructions on page 2) GWW				PETROLE			