Submit 3 Copies To Appropriate District State of New Mexico	Form C-103	
Office District I Energy, Minerals and Natural Resources	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II 1301 W. Grand Ava. Actoric NM 88310 OIL CONSERVATION DIVISION	30-025-00515	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	0. State Off & Gas Lease No.	
87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	3.50.5	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	MalMar Unit	
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number 214	
2. Name of Operator	9. OGRID Number	
Mar Oil and Gas Corp	151228	
3. Address of Operator	10. Pool name or Wildcat	
PO Box 5155 Santa Fe, NM 87502	Maljamar GB/SA	
4. Well Location		
Unit Letter N:660feet from the _South line and198	feet from theWestline	
Section 12 Township 17S Range 33E	NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, e		
Ti. Die van van van de van		
Pit or Below-grade Tank Application or Closure		
	Distance from nearest surface water	
	Construction Material	
I to Edited Tallottings.		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
, Elit Olivi (Cline)	PRILLING OPNS. P AND A	
	<u></u>	
PULL OR ALTER CASING	ENT JOB	
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion	
or recompletion.	2	
No pits will constructed during plugging operations X Notify NMOCD District 1 when	commence PA operation 505-393-6161	
8 5/8" 24# Casing set at 304ft X Cmt w/ 250sx cmt X Cmt circulated	02021222324	
5 1/2" 14# Casing set at 4457ft X Cmt w/ 300sx cmt X Estimated TOC 3019ft	5 ½" 14# Casing set at 4457ft X Cmt w/ 300sx cmt X Estimated TOC 3019ft	
Perfs 4101-4414ft X TS 1235ft X BS 2400ft	(A)	
Pens 4101-4414nt A 13 1253nt A B3 2400nt		
MISU X NU BOP		
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water	115 16 17 18 15 16 17 18 15 16 17 18 15 16 17 18 15 17 18 15 17 18 15 17 18 17 18 17 18 17 18 17 18 17 18 17 18 17 18 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug	2141516178 2001,000 2001	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug Pull tbg X perf casing at 2450ft Run realest X Set realest et 2100ft X Squeeze perfs with 50sx cmt X WOC	100 100 100 100 100 100 100 100 100 100	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug Pull tbg X perf casing at 2450ft Run packer X Set packer at 2100ft X Squeeze perfs with 50sx cmt X WOC	1,12,13,14,15,16,17,16,17,16,17,16,17,16,17,17,17,17,17,17,17,17,17,17,17,17,17,	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug Pull tbg X perf casing at 2450ft Run packer X Set packer at 2100ft X Squeeze perfs with 50sx cmt X WOC Tag plug X Pull tbg X Perf casing at 1200ft Pup packer X Set packer at 900ft X Squeeze perfs with 50 sx cmt X WOC	101 110 18 18 18 18 18 18 18 18 18 18 18 18 18	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug Pull tbg X perf casing at 2450ft Run packer X Set packer at 2100ft X Squeeze perfs with 50sx cmt X WOC Tag plug X Pull tbg X Perf casing at 1200ft Run packer X Set packer at 900ft X Squeeze perfs with 50 sx cmt X WOC Tag plug X Pull tbg X Perf casing at 354ft	1016 8 7 9 30 9 4 5 10 10 10 10 8 7 9 30 9 4 10 10 10 10 10 10 10 10 10 10 10 10 10	
MISU X NU BOP Run tbg X tag CIBP set 3986ft X Displace well with gelled brine water Spot 25sx cmt plug Pull tbg X perf casing at 2450ft Run packer X Set packer at 2100ft X Squeeze perfs with 50sx cmt X WOC Tag plug X Pull tbg X Perf casing at 1200ft Run packer X Set packer at 900ft X Squeeze perfs with 50 sx cmt X WOC Tag plug X Pull tbg X Perf casing at 354ft Circulate cement to surface Estimated at 100sx cmt	commence PA operation 505-393-6161	
Circulate cement to surface Estimated at 1005x cmt	201128314157671 1016878247 1	
Cut off well head and install PA marker	101/12/3/4/15/6/1/10/6/8/20/1/20/1/20/1/20/20/20/20/20/20/20/20/20/20/20/20/20/	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle	edge and belief. I further certify that any pit or below-	
Cut off well head and install PA marker	edge and belief. I further certify that any pit or below-	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle	edge and belief. I further certify that any pit or below-	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit  SIGNATURE  SIGNATURE  TITLE Foreman	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE <u>5/17/0</u> 7	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE  SIGNATURE  TITLE Foreman  Type or print name  Billy E. Prichard email address: shabillron01@warpdrived	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 5/17/07  Inline.comTelephone No.505-390-9100	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE  TITLE Foreman  Type or print name Billy E. Prichard email address: shabillron01@warpdrived For State Use Only	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 5/17/07  Inline.comTelephone No.505-390-9100	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit  SIGNATURE  TITLE Foreman  Type or print name  Billy E. Prichard email address: shabillron01@warpdrived  For State Use Only	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 5/17/07  Inline.comTelephone No.505-390-9100	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE  TITLE Foreman  Type or print name  Billy E. Prichard email address: shabillron01@warpdrived  For State Use Only  APPROVED BY: Lawwww. Troof-FIELD REPRESENT	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 5/17/07  Inline.comTelephone No.505-390-9100  ATIVE IL/STAFF MANAGER  DATE	
Cut off well head and install PA marker  RD MOSU X Cut off SU anchors X Clean and level location  I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines A general permit SIGNATURE  SIGNATURE  TITLE Foreman  Type or print name  Billy E. Prichard email address: shabillron01@warpdrived  For State Use Only  APPROVED BY:  Conditions of Approval (if any):  THE CONTROL OF SUMMER AND SUMER AND SUMMER AND SUMMER AND SUMMER AND SUMMER AND SUMMER AND SU	edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE <u>5/17/07</u> Inline.comTelephone No.505-390-9100	

BEGINNING OF PLUGGING OPERATIONS.