Submit 3 Copies To Appropriate District Office	<del>- ••••</del>				Form C-103 May 27, 2004
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources r., Hobbs, NM 88240			WELL API NO.	30-025-38313
District II 1301 W Grand Ave , Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type	of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV  1220 South St. Francis Dr. Santa Fe, NM 87505			STATE  6. State Oil & Ga		
1220 S. St Francis Dr., Santa Fe, NM 87505				BO-1626-0002	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name North Monument G/SA Unit	
PROPOSALS.)  1. Type of Well: Oil Well X Gas Well Other				8. Well Number 357	
2. Name of Operator Apache Corporation				9. OGRID Number 00873	
3. Address of Operator 6120 S Yale Ave, Suite 1500 Tulsa, OK 74136-4224				10. Pool name or Wildcat  Eunice Monument; Grayburg-San Andres	
4. Well Location					
Unit Letter B: 50 feet from the North line and 1330 feet from the East line  Section 36 Township 19S Range 36E NMPM CountyLea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3,617' GR  Pit or Below-grade Tank Application  or Closure					
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: m				onstruction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	CHANGE PLANS		REMEDIAL WOF	ILLING OPNS.	EPORT OF:  ALTERING CASING  P AND A
PULL OR ALTER CASING L	MULTIPLE COMPL		CASING/CEMEN		
OTHER:	unleted operations (Clearly	state all i	OTHER:Complet	ion Procedure ad give pertinent da	tes, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
05/17/07 PERF GRAYBURG @ 3924-44' 2 JSPF. 05/18/07 ACID W/ 1000 GALS 15% HCL. SWAB - ZERO % OIL CUT. NO GAS 05/21/07 SET CIBP @ 3920'. PERF GRAYBURG @ 3876-92' 2 JSPF. DMP 1 SX CMT ON CIBP TO PBD @ 3910'. 05/22/07 ACID GRAYBURG W/ 1000 GALS 15% HCL. SWAB - FOUND OIL AND GAS. 05/23/07 PU PUMP AND RIH W/ RODS. 05/24/07 SET 456 PUMPING UNIT. START GRAYBURG PRODUCTION.					
				/.	691011121374
				3031-1236 806	Received A
					2821207C7.77CU
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE Sophie.	Mackay	TITLE <u>E</u> n	gineering Tech		DATE 07/02/2007
Type or print name Sophie Mack	ay .		<u>-</u>		inlephone No. (918)491-4864
For State Use Only	1.0-	OC D	ASTRUCT SUPERVI	SOR/GENERAL M	ANAGER JUL 2 4 2007
APPROVED BY:	William	TITLE			DATE