

Office

District I

1625 N. French Dr., Hobbs, NM 88201

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Minerals and Natural Resources

Form C-103

June 19, 2008

RECEIVED
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBS OCE

WELL API NO.

30-005-10081

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E-9089

7. Lease Name or Unit Agreement Name

New Mexico BW State

8. Well Number 2

9. OGRID Number

245872

10. Pool name or Wildcat

Tobac Penn / Tobac Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Judah Oil, LLC

3. Address of Operator

P.O. Box 568, Artesia, NM 88211-0568

4. Well Location

Unit Letter _____ F : 1980 feet from the North line and 1980 feet from the West line

Section 20 Township 8S Range 33E NMPM County Chavez

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: Put back on Production ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached.

RECEIVED

AUG 28 2008

HOBBS OCE

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Manager/President

DATE 8/26/2008

Type or print name James B. Campanella

E-mail address: judahoil@yahoo.com

PHONE: 575-746-1280

For State Use Only

APPROVED BY:

PETROLEUM ENGINEER

DATE

AUG 29 2008

Conditions of Approval (if any):

Judah Oil, LLC

P.O. Box 568
611 Mahone, Suite D
Artesia, NM 88211-0568

Office- (505) 746-1280
Fax- (505) 746-1290
Cell- (505) 748-5488

judahoil@yahoo.com

New Mexico BW State #2

(Attachment to C-101 8-22-08)

Re-entry Procedure

MIRU Pulling Unit

NU BOP

RIH with 4-1/2" Bit, collars and 2-3/8 work string

Establish circulation

Drill CIBP @ 8150'

Drill CIBP @ 8894" and clean out to 9000'

POOH w/ work string and bit assembly

RIH w/ 2-3/8 seating nipple and work string to 8986'

Swab well to clean up and test

RIH w/ 4-1/2 air set packer and set @

Load backside with 70 bbls lease produced water

Pump 200 bbls lease produced water pad, follow w/ 5000 gal 15% HCL NEFE w/ 10% Glacial Acetic Acid w/ 10 gal surfactant. Pump in 3 stages as follows:

1st stg 2000 gal hot acid mix, drop 10 ball sealers, pump 2000 gal hot acid mix, drop 10 ball sealers,

Pump 1500 gal hot acid mix, flush with 50 bbls lease produced water.

POOH with packer and lay down work string.

RIH with 2-3/8 SN, 8990' production string.

ND BOP

RIH w/ Rod Pump

Put on production

Work to commence on 8-27-2008