Submit One Copy To Appropriate District Office	State of New Me	· · · · · · · ·	Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr. Hobbs, NM 882440			March 18, 2009 WELL API NO. /
District I  1625 N. French Dr, Hobbs, NM 88210  District II  1301 W. Grand Ave, Artesia, NM 88210  District III  1220 South St. Francis Dr			30-025-26005
District III 1000 Rio Brazos Rd., Aztec, NM 87410 AY 20 71115 Santa Fe. NM 87505			5. Indicate Type of Lease STATE X FEE
District IV Santa Fe, NM 87505			STATE X FEE  6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NMOBBSOCD  87505			B-1535
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			State F-1
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other			8. Well Number #8
2. Name of Operator			9. OGRID Number
ConocoPhillips Company  3. Address of Operator			217817 10. Pool name or Wildcat
P.O. Box 51810 Midland, Tx 79710			Eumont ·
4. Well Location			
Unit Letter 1: 1980 feet from the South line and 1980 feet from the East line			
Section 1 Township 21S Range 36E NMPM County Lea  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3487 GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
-			
NOTICE OF INT			SEQUENT REPORT OF:
	PLUG AND ABANDON  CHANGE PLANS	REMEDIAL WORK COMMENCE DRIL	
	MULTIPLE COMPL	CASING/CEMENT	
OTHER:			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)  All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.		t	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
1 / ) _			•
SIGNATURE		. Regulatory S	
Donna Williams Donna Williams			
For State Use Only  E-MAIL: @Conocophillips.com  PHONE: 432-688-6943			
APPROVED BY: Wall wh	TITLE (	min Allian	DITT 6/2/700 A
Conditions of Approval (if any):	IIILE (	UMJ. 47100	DATE 6/2/2009 ( released 1/29/2008)
			(14d Sed 7/29/2008)