

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

RECEIVED
OIL CONSERVATION DIVISION
JUN 10 2008
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBSSULL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35820
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator VANGUARD PERMIAN, LLC.		6. State Oil & Gas Lease No.
3. Address of Operator 7700 SAN FELIPE SUITE 485 HOUSTON, TEXAS 77063		7. Lease Name or Unit Agreement Name STATE "A"
4. Well Location Unit Letter A : 760' feet from the NORTH line and 500' feet from the EAST line Section 32 Township 18S Range 38E NMPM County LEA		8. Well Number #7
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3480' GL		9. OGRID Number 258350
		10. Pool name or Wildcat BYERS-QUEEN Hobbs Upper B.

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: SET CIBP AND TEMP ABANDON ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Moved in well service unit and rig up.
- Open well and bled pressure down to 0 PSI.
- Nippled down wellhead and pulled tubing.
- Rigged up wireline truck, pick up 5 1/2" CIBP ran in hole to 5830' and set plug. Ran dump bailer and set a 35' cement plug on top of CIBP. Plug back depth 5795'.
- Load hole with mud flange up wellhead and temporarily abandone well. 07/09/04.

Amending 2/23/05 C-103

Spud Date:

07/07/04

Rig Release Date:

07/09/04

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Joe T. Janica

TITLE Permit Eng.

DATE 06/10/09

Type or print name Joe T. Janica

E-mail address: joejanica@valornet.com PHONE: 575-391-8503

For State Use Only

APPROVED BY:

Larry W. Hill

TITLE

DISTRICT 1 SUPERVISOR

DATE

JUN 15 2009

Conditions of Approval (if any):

Well Diagram
State A #7
API: 30-025-35820

