
Submit 3 Copies To Appropriate District Office .	State of New Mexico		Form C-103 June 19, 2008
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II 1201 W. Grand Ava. Artaga N.M. 13 E. P. P. CONSERVATION DIVISION		30-025-38785	
District III 1000 Pro Prove Prince No. 97410 AUG 115 2001220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☐	
District IV 1220 S St Francis Dr, Santa Fe, NMHOBBSOCD Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
8/303	··		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT	
1. Type of Well: Oil Well Gas Well Other INJECTION		8. Well Number 438	
2. Name of Operator CHEVRON U.S.A. INC.		9. OGRID Number 4323	
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS	5 79705 PUL A 4 40 04		10. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES
4. Well Location BHL A-1-18s-34e, 30/N & 678/E			
Unit Letter A: 10 feet from the NORTH line and 420 feet from the EAST line			
Section 1 Township 18-S	Range 34-E	NMPM PVP PT CP ata)	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3986' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
		REMEDIAL WORK	
TEMPORARILY ABANDON			_
PULL OR ALTER CASING MU DOWNHOLE COMMINGLE	ILTIPLE COMPL	CASING/CEMENT	JOB \square
_			
OTHER:			WELL COMPLETION
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
3-20-09: MIRU. 3-21-09: PU BHA. TAG CMT @ 4138. DRILL OUT CMT 4138-4250. 3-22-09: DRILL CMT 4250-4599. 3-23-09: DRILL CMT 4599-4822. 3-24-09: DRILL CMT 4822-4916. RUN CPNL LOG. 3-25-09: RAN RAL LOG FR PBTD TO			
SURF. 3-26-09: PERF 4596-4750. ACIDIZE PERFS W/8500 GALS 15% HCL. 3-28-09: PERF 4762-4821, 4522-4560, 4474-4516.			
SET PLUG @ 4590. ACIDIZE 4474-45560 W/5000 GALS 15% HCL. PERF 4357-95, 4326-4352. SET PLUG @ 4468. ACIDIZE 4326-4395 W/5000 GALS 15% HCL. SET PLUG @ 4468. 3-29-09: TIH W/BHA TO 4290. CIRC 100 BBLS 2% KCL. DRILL ALL 3			
PLUGS @ 4303, 4470, 4590. 3-31-09: ACIDIZE 4762-4821 W/2500 GALS 15% HCL. REL PKR. 4-01-09: REL PKR. EOT @ 4262.			
4-02-09: MOVE IN 2 3/8" TBG. SET PKR @ 4261. CIRC 2% KCL PKR FLUID. 4-03-09: NU CO2 WH. CHART & TEST TO 500#. GOOD. (ORIGINAL CHART & COPY OF CHART ATTACHED). RIG DOWN. FINAL REPORT W/O TEST.			
4-23-09: INJ'G 629 BWPD @ 629 PSI 5-02-09: INJ'G 1312 CO2 @ 1276 PSI			
4-23-09: INJ'G 629 BWPD @ 629 PSI	* H	In section) List
5-02-09: INJ'G 1312 CO2 @ 1276 PSI	71		
6 1844	D' D I D		
Spud Date:	Rig Release Date	e:	
			R-4442-C
I hereby certify that the information above	is true and complete to the bes	t of my knowledge	and belief.
SIGNATURE / VIMBO PANS	State rec	GULATORY SPEC	IALIST DATE 08-04-2009
Type or print name DENISE PINKERTOR For State Use Only	N E-mail address: <u>le</u>	akejd@chevron.com	
DISTRICT 1 SUPERVISOR			
APPROVED BY:	TITLE		DATE
Conditions of Approval (if airsy).			



Max los 35 35 Ser Rugs Ser Rugs Ser Rugs Ser

(