Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCDRECEIVED

FORM APROVED OMB NO 1004-0135 EXPIRES: March 31, 2007

МИЛ

SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No. JUN 30 2010 LC-062391 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals HOBBSOCD SUBMIT IN TRIPLICATE 7 Unit or CA Agreement Name and No. 1a. Type of Well Gas Well Oil Well Other 8 Well Name and No. Kachina 5 Federal 4 2 Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 9 API Well No. 30-025-31690 3 Address and Telephone No. 10. Field and Pool, or Exploratory 20 North Broadway, Oklahoma City, OK 73102-8260 Corbin Wolfcamp, South 4. Location of Well (Report location clearly and in accordance with Federal requirements)\* 1980 FNL & 1980 FEL Sec 5 T18S R33E, Unit G 11. County or Parish State

		·		14111 -	_
	K APPROPRIATE BOX(s) TO		OTICE, REPORT, OR OTHER DA	ТА	_
TYPE OS SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other	_
13 Describe Proposed or Completed Operations (Caleepen directionally or recomplete horizontally, give s					
200por an occornant or recomplete monte many, give o				•	

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration inferior if the propose deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection).

Devon Energy Production Company, LP respectfully requests approval to plug back the Wolfcamp and test the Bone Spring formation.

- MIRU. Unseat pump and TOH with pump and rods.
- 2. ND wellhead and NU BOP. TOH with tubing.
- 3. TIH with bit and scraper. TOH
- 4. TIH with CIBP and set at +/- 11,165'. Test casing and CIBP.
- 5. RIH and perforate Bone Spring from 8825'-8877' and 8925'-8960', 2 SPF with 0.43 EHD holes.
- 6. TIH with treating packer and set at  $\sim$  8810'. Spot with 7.5% HCl acid followed by 51 bbls 2% KCl. Pull packer and set at  $\sim$ 8,575'.
- 7. Acidize and frac per recommendation. Flow well back.
- 8. Unset packer and TOH with tubing and packer. TIH with tubing. ND BOP and NU wellhead.
- TIH with pump and rods.
- 10. RDMO. Return well to production.

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

		., . ,
	Norval RenROVED	Date 6/11/2010
(This space for Federal or State Office use)  Approved by Conditions of approval, if any.	JUN 2 8 2010  /s/ Dustin Winkler	JUL 0 1 2010
Tibe א ט ס כ Section ויסטד, makėš ir a ciline ibi ariy person knowingry and williony to make ariy depart within	nenr <b>地址的证外句 证时</b> 可能 <b>相关证明外间接所提例有</b> or in its junsdicti <mark>@ARLSBAD FIELD OFFICE</mark>	addient statements or representations to any matter

\*See Instruction on Reverse Side

Dir.

Devon Energy Production Company, LP NMLC-062391- Kachina 5 Federal #4 API: 30-025-31690 Lea County, New Mexico

RE: Plug back/Recompletion - Conditions of Approval

There is to be no surface disturbance beyond the originally approved pad without prior approval. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

- 1. CIBP will have 35' bailed or 25sx pumped Class H cement on top of it.
- 2. Top of Wolfcamp plug will need to be addressed when plugging the well, or plugging back further up hole.

Submit subsequent report with accurate wellbore schematics and completion report once work is completed.

DHW 062510