

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
March 4, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-025-33774
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron U.S.A Inc		6. State Oil & Gas Lease No.
3. Address of Operator #15 Smith Rd., Midland, TX 79705		7. Lease Name or Unit Agreement Name New Mexico E State NCT-1
4. Well Location Unit Letter <u>N</u> : <u>990</u> feet from the <u>South</u> line and <u>1855</u> feet from the <u>West</u> line Section <u>1</u> Township <u>20-S</u> Range <u>36-E</u> NMPM Lea County		8. Well Number 7
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 4323
		10. Pool name or Wildcat Monument Blinberry

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL N Sect 1 Twp 20-S Rng 36-E Pit type Steel Depth to Groundwater _____ Distance from nearest fresh water well Over 1000'
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
990 feet from the South line and 1855 feet from the West line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CAS ☐
CE ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well completion or recompletion.

1. Notify OCD 24 hrs. prior to MI and RU.
2. RIH set CIBP@5600' and spot 25sx cement plug from 5600'-5400'.
3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
4. Perf and squeeze 95sx cement plug from 2540'-2140' (Yates/B-Salt est.). WOC&TAG
5. Perf and squeeze 160sx cement plug from 1270'-950' (shoe/T-Salt est.). WOC&TAG
6. Perf and squeeze 200sx cement plug from 400'-surface' (Fr. Water/surface) WOC&TAG
7. Install dryhole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE M. Lee Roark TITLE Agent for Chevron USA, Inc. DATE 10/11/2010

Type or print name M. Lee Roark E-mail address: _____ Telephone No. 432-561-8600

(This space for State use)

APPROVED BY [Signature] TITLE STAFF MGR DATE 10-13-10
Conditions of approval, if any: _____

[illegible]

[Ground Elevation (MSL):-] 0.00 [Spud Date] 01/01/1900 [Compl. Date] 01/01/1900
[Well Depth Datum:] Kelly Bushing [Elevation (MSL):-] 0.00 [Correction Factor] 0.00
[Last Updated by] jackssi [Date] 01/07/2008
[null] null [null] null

SECT 1 TWN 20S RNG 36E
FROM 990' N(S) 1055' E(N) L
TD: 7500' FORMATION @ TD
PBTD: FORMATION @ PBTD

