State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-200

FILE IN TRIPLICATE	RECEIVEDSERV	ATION DIVISION		Revised 5-27-2004
DISTRICT I	1220 South	h St. Francis Dr.	WELL API NO. 30-025-05468	
1625 N. French Dr., Hobbs, NM 88240 DISTRICT II	DEC 1 4 2010 Santa Fe	, NM 87505	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210	HOBBSOCD		STATE X	FEE
DISTRICT III	MODDOOO		6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	CONTORIO ANTO DEPONDO ON HIE	DI I G	7 Laga Nama an Unit Amazon	ant Name
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Unit Section 23	
1. Type of Well:			8. Well No. 412	
Oil Well	Gas Well Other 7	Temporarily Abandoned	0.00010.)	<i>-</i>
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, 7	X 79323			
Unit Letter A : 990	Feet From The North			Line
Section 23	Township 18-S 11. Elevation (Show whether DF, F	Range 37-E	NMPM	Lea County
	3670' GL	KKB, RI UR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	NS. PLUG & A	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	T JOB	
OTHER:		OTHER: MIT test failur	e repair/TA Status Request	X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. RUPU & RU. 2. NU BOP/ND wellhead. RUPU 11/01/2010 RDPU 11/09/2010				
3. Isolate casing leak from 110-180'.				
4. Squeeze casing leak w/6.2 bbl of cement.5. RU bit & drill collars. Drill cement from wellhead to 270'. Chased cement stringers to 320'. Circ clean.				
6. Test squeeze. Tested OK.				
7. POOH w/bit & drill collars.				
8. Test casing to 560 PSI for 30 minutes and chart for the NMOCD.9. ND BOP/NU TA wellhead.				
10. RDPU & RU. Clean location Leave well TA"d. CIBP set @3953 w/35' of cement on top/Perfs 3990-4204' Abandonment Expires				
I hereby certify that the information above	is true and complete to the best of my kno	wledge and belief I further certify t	hat any pit or below-grade tank h	as heen/will be
constructed or		_		
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE MUNCLE Administrative Associate DATE 12/10/2010				
TUDE OF PROTECTION				
For State Use Only	Joinson (E-njan address)	mendy Johnson (a) oxy, com	TELEPHONE NO.	806-592-6280
APPROVED BY	3 1	TITLE STATE		E 12-16-10
CONDITIONS OF APPROVAL IF ADV:				
CONDITIONS OF AFTROVAL IF ALVI.	\cup		,	

