

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: SANTA FE PACIFIC "SODW" Well No. 4

Field: CROSSROADS DEVONIAN

County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. M.I.P.W. RUN TUBING O.E. TO P.B.T.D. AND
SPOT 25 SA CEMENT PLUG
2. CIRCULATE HOLE TO MWD LADEN FLUID
3. PULL TUBING AND SPOT 10 SA CEMENT
PLUG @ SURFACE.
4. CHT OFF WELL HEAD - AND INSTALL MARKER

NOTE: NO CASING AVAILABLE FOR ECONOMIC
SALVAGE