Submit 3 Copies to Appropriate
District Office

tate of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

P.O. Box 1980, Hobbs, NM 88240	DISTRIC P.O. Box	T.J 1980,	Hobbs,	NM	88240
--------------------------------	---------------------	--------------	--------	----	-------

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1100 Rio Brazos Rd., Aztec, NM 87410

OIJ, CONSERVATION DIVISION

SUNDRY NOTICES AND REPORTS ON WELLS

		P.O.	Box 208	38
Santa	Fe,	New	Mexico	87504-2088

esources Department	Kenima 1-1-02
ON DIVISION	WELL API NO. 1 30-025-03607
87504-2088	5. Indicate Type of Lease STATE FEE
	6. State Oil & Gas Lease No.
110	
LLS YON PLUG BACK TO A ERMIT	7. Lease Name or Unit Agreement Name
	U. D. SAWYER
	8. Well No.
	9. Pool name or Wildrat Crossroads Siliero Devan
Line and198	80 Feet From The EAST Line
Range 36 E. T.DF, RKB, RT, GR, etc.)	NMIN LEA CO. County
r DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
Nature of Notice. I	Report, or Other Data
	BSECUENT REPORT OF:
REMEDIAL WORK	ALTERING CASING
COMMENCE DRILLIN	IG OPNS. PLUG AND ABANDONMENT $[X]$
CASING TEST AND C	f1
OTHER:	
and give pertinent dates, inc	luding estimated date of starting any proposed
1,375 W/35' ON 1 O#/MUD. PULL TO	TOP (12/12/89) D 7000' MIX AND PUMP 100' (25 SXS)
) POH (12/20/89	Θ)
DID NOT TAG NOT TAG NOT TAG NOT TAG PLUG @ 38 NOT TAG PLUG @ 38 NOT TAG NOT TA	PLUG. (1/2/90) 850'. (1/3/90) 318'. (1/8/90)
SELLAR. (1/9/90)
and belief.	4/40/00
TIME VICE-PRESID	ENT PARE 1/10/90

DIFFERENT RESERVOIR. LISE "APPLICATION FOR PER (FORM C-101) FC 3 SUCH PROPOSALS.)	7. Lease Name of Unit Agreement Name
1. Type of Well: OIL GAS OTHER	U. D. SAWYER
2. Name of Operator	8. Well No.
ORYX ENERGY COMPANY	1
3. Address of Operator	9. Pool name or Wildrat
P.O. BOX 1861, MIDLAND, TX 79702	Crossroads Siluro Devan
4. Well Location Unit Letter0 :660 Feet From TheSOUTH	Line and 1980 Feet From The EAST Line
	inge 36 E IJMPM LEA CO. County
11. Check Appropriate Box to Indicate I	Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSECUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT X
	CASING TEST AND CEMENT JOB
PULL OR ALTER CASING	171
OTHER:	OTHER:
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.	
CEMENT. PULL TUBING (12/19/89) 3. RIIN TBG TO 4800'. MIX AND PUMP (25 SXS)	FILE TO 7000 TITA AND TOM TOTAL
4. CUT AND PULL 3400' OF 5-1/2 CSG.	DID NOT TAG PLUG. (1/2/90)
5. RAN TBG TO 3823'. MIX AND PUMP 65 SXS.	(4.12.100)
6. RAN TBG TO 3823'. MIX AND PUMP 65 SXS.	(4 (0 (00)
7. RAN TBG TO 3507'. MIX AND PUMP 65 SXS.	10.000
8. PULL TBG TO 2212'. MIX AND PUMP 45 SXS 9. INSTALL DRY HOLE MARKER, LEVEL PIT & CE	J. 1022 10 8811111821

OIL & GAS INSPECTOR

true and complete to the best of my knowledge and belief.

CHRIS PRICKETT

TYTE OR FRINT NAME

(This space for State Use)

CONDITIONS OF AIT ROVAL, IF ANY:

KWA, INC.

111 ET KNE NO. (915)697-3265