

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	OK 30-025-03607
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	U. D. Sawyer
8. Well No.	1
9. Pool name or Wildcat	Saline Seawater Crossroads (Parr)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4041.5 KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	Oryx Energy Company
3. Address of Operator	P.O. Box 1861, Midland, Texas 79702
4. Well Location	Unit Letter <u>0</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line

Section <u>27</u>	Township <u>9-S</u>	Range <u>36-E</u>	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PU. ND WH. NU BOP. RLSE BAKER MOD. R-3 DG PKR @ $\pm 11314'$. CIRC HOLE FULL W/9.5 LB/GAL BRINE W/25 LB/BBL SALT GEL. POH W/2-7/8", 6.5#, C-75 & J-55 PROD TBG LAYING DOWN $\pm 6400'$ (STAND BACK $\pm 4900'$).
- MIRU APOLLO WL. DUMP BAIL 35' (3.3 SKS) CLASS "C" NEAT, 1.32 CU FT/SK YIELD ON TOP OF CIBP @ $\pm 11475'$. WL SET 5-1/2", 20# CIBP @ $\pm 11380'$ VIA GEARHART-OWEN GR/NEUTRON/CCL DATED 4-30-80. DUMP BAIL 35' (3.3 SKS) ON TOP. PERF 4-WAY SQZ HOLE @ ± 3710 (INTERMEDIATE CSG SHOE). PERF 4-WAY SQZ HOLE @ ± 2220 (TOP OF SALT). RD APOLLO.
- RIH W/2-7/8" PROD TBG OE TO $\pm 4900'$. SPOT 20 SKS CLASS "C" NEAT CMT PLUG FROM 4900-4688. WOC $\pm 2-3$ HRS, TAG TO CONFIRM DEPTH. POH. Continued Page 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE Accountant DATE 7-31-89

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 7 1989

CONDITIONS OF APPROVAL, IF ANY: _____

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

4. RIH W/5-1/2", 20# BAKER RDG PKR ON 2-7/8" TBG TO ± 3600 . EIR SQZ HOLES @ $\pm 3710'$. RAISE & SET PKR @ $\pm 3450'$. SQZ W/70 SKS CLASS "C" NEAT CMT. DISPLACE 50 SKS INTO SQZ HOLES, LEAVING ± 20 SKS BELOW PKR. WOC, RLSE PKR & TAG TOP OF CMT.
5. RAISE & SET PKR @ $\pm 1900'$. EIR SQZ HOLES @ $\pm 2220'$. SQZ W/70 SKS CLASS "C" NEAT CMT. DISPLACE 50 SKS INTO SQZ HOLES, LEAVING ± 20 SKS BELOW PKR. WOC, RLSE PKR & TAG TOP OF CMT.
6. SPOT 10 SKS ($\pm 100'$ CMT) FROM 100' TO SURFACE.
7. CUT OFF WELLHEAD 4' BELOW GROUND LEVEL. WELD ON STEEL PLATE & MARKER. CLN LOCATION. RLSE RIG.