

NO. OF COPIES RECEIVED	
DISTRIBUTION	
AMTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR RE-LOCATE TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - C-101 FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Sun Oil Company

Address of Operator
P. O. Box 1861, Midland, TX 79702

Location of Well
UNIT LETTER **A** **660** FEET FROM THE **East** LINE AND **660** FEET FROM
THE **North** LINE, SECTION **27** TOWNSHIP **9-S** RANGE **36E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4027 Gr.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
U. D. Sawyer

9. Well No.
4

10. Field and Pool, or Wildcat
Crossroads Penn.

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WILL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☒
		plug back	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-12-78 1. Move in & rig-up. DA&S Well Service.
2. Ran CIBP to 12,010'.
3. Ran 4" Dump Bailer (4 1/8" shoe) w/2 sxs cement to 6860; unable to lower. P.O.H.
12-13-78 1. Ran 3 1/2" OD Dump Bailer & dump 4 sxs cmt on CIBP @ 12,010'-11,974' TOC.
2. Load csg. w/14 bbls. S.W. & test csg. to 500 P.S.I. OK.
3. Wellex perf. 11,442-450', 1 shot per ft.
12-14-78 1. Ran 2 7/8" tbg. w/pkr. to 8300'.
12-15-78 1. Circ. hole w/457 bbls. 2% KCL Wtr. w/additives.
2. Disp. 150 bbls. & spot 100 gals 15% HCL @ 11,450-11,324'.
3. Install Nat'l Wellhead Assy.
4. Acidize perfs 11,442-450' w/1300 gals 15% HCL w/20 ball sealers. Brk. Down press. 3400#.
5. 1 hr., start swab. Back load water. F.L. 7200-7600.
12-16-78 Swab 140 BLW & 10 BO. Fair Gas blow.
12-17-78 1. 14 hr., SITP 550#.
2. 3 hrs. flow 18/64 CK., 50 BO & 0 Wtr.
12-18-78 1. 20 1/2 hrs., flow 437 BO & 27 BW 15/64 CK.
2. CK. w/N.M.C.C. for test allow.
12-19-78 1. Flow 467 BO & 0 BW, 12/64 CK., T.P. 950#.

(Continued on attached page)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Charles Randolph TITLE **OFFICE Asst.** DATE **12-26-78**

APPROVED BY _____ TITLE _____ DATE _____

ADDITIONS OF APPROVAL, IF ANY: