- 8. Reperforated 7" casing with 20 holes from 9671 to 9676'. T.D. 9694'. Tubing swabbed dry; no shows.
  - (a) Acidised with 500 gals. mud acid. Swabbed salt water with 7700' of fluid in bals.

Squeezed 45 sax thru perforations 9671 to 9676'. Drilled out to 9676'.

9. Perforated 72 holes from 9663 to 9673'. Tubing swabbed dry.

(a) Acidized with 1000 gals. Swabbed salt water with 7800' of fluid standing in hole.

Squeezed 46 sax thre perforations; final pressure 4100 psi. T.D. 9676'.

10. Perforated 32 holes from 96k7 to 9651'. Packer set at 9618'. T.D. 9657g'. Swabbed dry; no shows.

(a) Attempt acidize with 500 gals. mud acid failed.

11. Perforated hh holes from 9631 to 9636'. Packer at 9618'.

(a) Acidised with 500 gals. mud acid. Swabbed 20 barrels per hour salt water with fluid standing 7700' in hold.

Squeezed 12 sax thru perforations 9631 to 9636'. Final pressure 4300 psi. Brilled out to 9680'.

12. Perforated 40 holes from 9669 to 9676'. Tubing swabbed dry.

- (a) Attempt to acidize with 500 gals. failed; formation would not break. Ran Baker R C tool and set at 9555'.
- (b) Acidized with 500 gala; formation broke at 5000 psi. swabbed salt water at rate of 23 barrels per hour with 7850' of fluid in hole; no shows.

Squeezed 30 sax three perforations 9669 to 9676'. Drilled out to 9685'.

13. Perforated 20 holes from 9680 to 9685'.

(a) Acidized with 500 gals; formation broke at 5200 psi. Swabbed salt water at rate of 23 barrels per hour with 7650' of fluid in hole; no shows.

Set plug at 9594'.

14. Perforated 19 holes from 9581 to 9586'. Swabbed salt water at rate of 18 barrels per hour; 5600' of fluid standing in hole. T.D. 9594'.

Set plug at 9448'.

- 15. Perforated 20 holes from 9436 to 9441'. Swabbed dry; no shows.
  - (a) Attempt to acidize failed; formation would not break.

Set bridging plug at 9284'.

16. Perforated 15 holes from 9262 to 9275'. Packer at 9147'.

(a) Acidised with 500 gals. Swabbed a small amount of salt water off bottom; no shows.

J.--

(c) leftilsed with (0) gals, and other stars with a dec with (100° of flade in Cale.

Squeesel 15 Fun to reconstitute MCG to SAMP. Friled

- . The reddome mails " . (Eth) of (6) wor realed ST bosersberg" .
- (a) defined with LCC wells. Invelocit and takes with (-201)
  of fluid standing in only.

Squeened his and Uru conformationes from preserve M10. 561. 3.0. 20751.

A. Prigrated 32 Poles from Staff to S Sit. Include so Staff. 1.1. Sov M. Mashed dry; to sums.

.ioftal this material CCC fifth endine damath (s)

- I. Furtherated in toles from 96, 1 to 7, 301. Protect of 942.
- (a) softward to have selen and selen automated to have a second secon

iqueers 12 ers vira perforctions for the to the first strate. Minel

- 13. Erforated in Inter ( ) States of Mark an Arte. In Lang arabbed dry.
- (a) Stampt to active att. 400 wile. Pattery "creation world not pread. Law likes - tool and att att 98554.
  - (e: Adddeet with fit ,sle; Adructics assis at 5000 met. Amelded sait mater at mits of 23 cample nom noum with 7350: of Mois in bole; r - acome.

squeered H eas for a sufficience for an offs, and here

- 13. entorated 2) heles from 9630 to 16851.
- (a sold and relability yalo; for relation order to 2200 mml. Swabbs and a mater at rate of 23 carrely our base for 7600 of flored for holder to choose.

HERE SECTION SECTION

 Inforebod 15 holes from 95% by 95%. Involved sold water to row of 15 bornels certaint 960% of State second of Hole. . ... PERS.

Set ala as all to

. and the test of the first the first the first sector of the factors . I

. Second to realize the test the form each term of toposts. (a)

Address and principal test

1. Sentended IF of a low first and set a time and the battering of the

s der dise is drassi i Lang ( som eine . 128, 007 s(the Scaritar (e)

.