



APPROVAL

(SUBMIT IN TRIPLICATE)

Land Office

Lease No. **NM 0359268**

Unit

SEP 17 1964
UNITED STATES
DEPARTMENT OF THE INTERIOR
J. L. GORDON
Geological Survey

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 7, 1964, 19.....

Well No. 1 is located 2310 ft. from N line and 2272 ft. from E line of sec. 31NW 1/4, Sec. 31 (1/4 Sec. and Sec. No.) 36E (Twp.) NM 18N (Range) (Meridian)West Crossroads (Field) Lea (County or Subdivision) New Mexico (State or Territory)The elevation of the derrick floor above sea level is 4079 ft.**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

May 7 through Aug. 19, 1964

5 1/2" liner was perforated as follows:

10, 567-78; 10, 501-06; 10, 276-80; 9851-54; 9755-59; 9672-77; 8917-27 and 4877-83.

All zones produced salt water on tests.

Spotted cement plugs as follows:

40 sx from 10, 670 to 10, 230

20 sx from 4, 890 to 4, 715

90 sx from 9, 900 to 9, 140

20 sx from 4, 623 to 3, 917

20 sx from 8, 927 to 8, 830

30 sx from 90 to surface

Place 4" pipe marker in cement at surface. Filled pits and levelled location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MWJ Producing CompanyAddress 413 First National Bank Bldg., Midland, TexasBy Edward H. JudsonTitle V. Pres