



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. RM 0359268

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT <u>X</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 1, 1964, 19

Well No. 1 is located 2410 ft. from N line and 2272 ft. from E line of sec. 31
N 1/4, Sec. 31 (1/4 Sec. and Sec. No.) 7-5 (Twp.) 30E (Range) 100W (Meridian)

East Crossroads (Field) Lea (County or Subdivision) New Mexico (State or Territory)
The elevation of the derrick floor above sea level is 4079 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

May 7 through Aug. 19, 1964

5 1/2' liner was perforated as follows:

10,567-76; 10,501-06; 10,276-58; 9551-52; 9755-59; 9672-77; 8917-27 and 4877-83.

All zones produced salt water on tests.

Spotted cement plugs as follows:

40 sx from 10,670 to 10,230

20 sx from 4,890 to 4,715

50 sx from 9,900 to 9,140

20 sx from 4,023 to 3,917

20 sx from 8,927 to 8,830

10 sx from 90 to surface

Place 4 pipe marker in cement at surface. Filled pits and levelled location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company M J Producing CompanyAddress 413 First National Bank Bldg., Midland, TexasBy Edward H. JudsonTitle V. Pres