#17 continued - Attachment #1

- 10/10/82 (cont.) seal assm for Baker Model D pkr, rec a 41' sliver of 4-1/2 tbg (btm 6 jts of 4-1/2 tbg & piece 2-7/8 tbg was plugged w/ iron sulfide) prep to run 8-1/8 cutrite shoe & 1 jt WP w/ catchers & run to top of liner, model D set 4475.
- 10/11/82 WIH w/ 8-1/8 ODx7-3/16 ID x 3' cutlip-cutrite shoe w/ wire & tension spring catchers inside shoe, 1 jt 7-3/8 WP, BS on 2-7/8 tbg, tag @ 4414 & work shoe dn to 4435, circ hole 1 hr, rec 5 gals iron sulfide, mill hanging & torquing, POH, LD WP.
- 10/12/28 Corr washover depth 4401, WIH w/ 8-1/4 ODx4" IDx4' shoe, 1 jt 7-3/8 WP, BS on 2-7/8 tbg to 4401, work mill down to 4428, washing out iron sulfide, circ hole clean, rec 2 gals metal cuttings & 6' piece of 2-7/8 tbg & 5' sliver of 4-1/2 twisted tbg, shoe had 5-1/2 ring worn on btm ind liner top.
- 10/13/82 WIH w/ 4-5/8 OD x3-13/16 ID Cutrite shoe, 2 jts 4-1/2 WP, 7-1/4 string stablz, BS on 2-7/8 tbg, tag @ 4428, milled 4428-4432, stop going, circ out iron sulfide, red bed, cmt & metal cuttings, circ hole clean, POH w/ shoe, shoe worn smooth, WIH w/ new shoe, same assm to 4200.
- 10/14/82 Fin GIH w/ shoe, tag @ 4429, milled on junk 2 hrs, 1' to 4430, stop going, POH, mill worn smooth, ind tbg fish being up inside shoe 2', WIH w/ 4-5/8 CB mill, 7-1/4 string stabz, BS to 4400.
- 10/15/82 Fin GIH w/ mill to 4428, CO red bed & iron sulfide to 4430, milled 6" stop going, POH ind on stab running on 5-1/2 liner top, WIH w/ 4" mgt on SL 2 runs, rec qt metal chips, WIH w/4-5/8 concave mill, 1 jt 2-7/8 tbg, 7-1/4 stab, BS, 2-7/8 tbg to 4430-1/2, milled 4430-1/2-4432-1/2 - 4 hrs, circ clean.
- 10/16- Cont milling on junk tbg to 4434/18" / 5 hrs, circ clean, POH w/ mill, WIH
  17/82 w/ 4-5/8 OD, 3-13/16 ID wavy btm mill, 2 jts 4-1/2 WP, 7-1/4 stab, BS, jars,
  4 4-3/4 cols on 2-7/8 tbg to 4420.
- 10/18/82 W0 fish 4432-4434/4 hrs, POH w/ shoe, shoe worn smooth, rec 18" piece of 2-7/8 tbg caught inside of shoe, WIH w/ new shoe, same assm, milled 4434-4435 1-1/2 hrs, pulled up clear, circ hole clean.
- 10/19/82 Cont milling over fish 4435-4436/1'/3 hrs, POH w/ shoe, shoe worn smooth, WIH
  w/ same tools, mill over fish 4436-4461/25'/1 hr, mill stop going, circ hole
  clean.
- 10/20/82 POH w/ shoe, shoe worn smooth, rec 17' piece 2-7/8 tbg in WP, leaving T/fish @ 4454, WIH w/ new mill, same assm, mill over fish 4454-4473, POH w/ shoe, rec all of fish - 25' piece 2-7/8 tbg, 2-3/8x2-7/8 swedge & Baker seal assm, WIH w/ 4" mgt, 1 jt 2-7/8 tbg on SL to 4475, no rec, WIH, LD 50 jts 2-3/8 tbg.
- 10/21/82 WIH w/ 9-5/8 Baker FB pkr, 1 jt 2-7/8 tbg, set pkr @ 29', fill csg w/ fr wtr, rpr holes in 9-5/8 csg @ surf, pull pkr, WIH w/ Baker RD plug, 2 jts 2-7/8 tbg, Baker 9-5/8 pkr on 2-7/8 tbg, pkr stopped @ 2486, could not work deeper 1/2 hr, POH, LD pkr, WIH w/ DR plug, latch into 5-1/2 Baker N pkr @ 4475, pull tbg to 4400.
- 10/22- Spotted 3 sxs sd down 2-7/8 tbg, WO sd 30 min, attempted to tag sd, no
- 23&24/82 fill, POH w/ tbg, RIH w/ 4-1/2 OS, 3 1/16" grapple on 2-7/8 tbg, latched onto Baker DR plug @ 4475, POH w/plug, had hole in btm of DR plug, "O" rings washed up on latch assembly, SDFN & weekend, prep to run new DR plug.
- 10/25/82 WIH w/Baker DR plug, 1 jt 2-7/8 tbg, Baker 5" R pkr on 2-7/8 tbg, set DR plug in Baker N pkr @ 4475, could not set R pkr, POH w/pkr, pkr looked OK, WIH w/new Baker R pkr, could not get in top of 5" liner @ 4448, POH w/pkr, btm of pkr had iron sulfide caked in slips.
- 10/26/82 WIH w/4-3/4" bit, 5-1/2" CS on 2-7/8 tbg, clean out rough csg 4448-4473/ 3 hrs, POH w/bit, WIH w/5-1/2" Baker R pkr on 2-7/8 tbg to 4470, set pk pump down tbg, could not get press, ISIP strong vac, unseat & POH w/pkr.
- 10/27/82 WIH w/4-11/16" OS, 3-1/16" gpl on 2-7/8 tbg, could not latch onto DR plug @ 4475, POH WIH w/4-11/16" short catch OS, 3-1/16" gpl, could not latch onto DR plug, POH WIH w/same tools 3" gpl, latch onto DR plug @ 4475, POH rec same, btm of plug marked as if having junk in N pkr.
- 10/28/82 WIH w/Baker 5-1/2" RBP & R pkr on 2-7/8 tbg, tag N pkr @ 4475, set BP @ 4470, pkr @ 4465, attempt to press test BP leaked on vac, POH w/BP & pkr, WIH w/Baker 5-1/2" bull plugged Locset pkr, Baker R pkr, set plugged

PEC R 1982 HOUSES COMICE