

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR OPERATIONS ON WELLS OR PRODUCTION FROM A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL AND C-102 FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	5a. Indicate Type of Lease State ☐ Fee ☒
2. Name of Operator TEXACO Inc.	5. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER G 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 34 TOWNSHIP 9-S RANGE 36-E N.M.P.M.	8. Form of Lease Name U. D. Sawyer
15. Elevation (Show whether DF, RT, GR, etc.) 4029' (GR)	9. Well No. 1 2
	10. Field and Pool, or Wildcat Crossroads Devonian
	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull Reda pump and tubing.
2. Set packer @ 12,118' w/tailpipe @ 12,018'.
3. Acidize 5-1/2" OD csg perforations 12,176-12,180' w/3000 gals 20% NE acid, 165 gals SP-203 scale inhibitor.
4. Flush w/100 BSW.
5. Pull packer.
6. Install submersible pump. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **Asst. Dist. Supt.** DATE **3-31-76**

APPROVED BY _____ TITLE _____ DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

1970
CORPORATION
1970